

(08/1/22) waf

ASS. IEC. BY:

REF:

CC3/CT12207414/Rea3

369K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 6320X

at Workshop m/s

STRIDES COMPT

of

60, Monmouths Ind Plk E4

Insured:

CTI

Policy No.

Claim No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. O/Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 6320X

Yr Regn: 2017 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIMS HYBRID 1.8 COM C.C 1798

Colour:

MAROON

A/C: Insured / Std / NI / NA

Sp. Reading

463487

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J70KB3FU303373374

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SAILUN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

03/08/22

D.O.I.

03/08/22

Survey held at

STRIDES

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

)

S + RS, SI

☐

: Interview (\$

)

: Photos

☐

: Tech. Invs (\$

)

: Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Case Details

Case Reference Number :
TAX/08/22/2004
Type of Repair : Accident Repair
Vehicle Registration Number :
SHD6320X

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-18995-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
Accident Date and Time : 03/08/2022 03:23 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.9	Replace	de
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.1	Replace	H
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	re
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	re
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	re
Standard	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	re
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Check	?
Standard	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xm
Standard	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	?
Standard	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	Xm
Standard	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	?
Standard	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xm
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	re

Total Spare Part Cost 12,293.58

Surveyor Total 5,097.77

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 0

Final Spare Part Cost 9,452.42

Final Sur Total 5,097.77

SMRT Recommendation											Surveyor Approval				Remarks	BOM Type
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace			
Standard	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.7	Replace	✓	de	
Standard	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	✓	con	
Standard	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	✓	Xan	
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	✓	sc	
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	✓	hu	
Standard	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	✓	?	
Standard	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	0	0	Check	✓	?	
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	1	394.2	Replace	✓	con	
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✓	Xan	
Standard	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check	✓	?	
Standard	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	✓	Xan	
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	0	0	Check	✓	?	
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give	✓	Xan	
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	✓	Xan	
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	✓	Xan	
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	✓	Xan	
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	0	Repair	✓	R	
Standard	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.53	Replace	0	0	Check	✓	?	
Standard	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	2	0.00	Replace	✓	hu	

Total Spare Part Cost 12,293.58

Surveyor Total 5,097.77

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 0

Final Spare Part Cost 9,453.42

Final Sum Total 5,097.77

Remarks

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	668.4	Replace	Can
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	Can
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	Can
Standard	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	1,569.70	25.00	1,177.28	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	725.90	25.00	544.43	Replace	1	544.4	Replace	Can
Standard	Main			SEALANT W/SCREEN (3PCS)	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE TRIM , UPPER	1	50.50	50.50	25.00	37.88	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE TRIM , RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE TRIM , LH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE TRIM , LOWER	1	218.50	218.50	25.00	163.88	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Check	?
Standard	Main			TAILGATE BOARD , COVER	1	24.10	24.10	25.00	18.08	Replace	0	0	Check	?
Standard	Main	VM		CLIP(FOR FRONT BODY PILLAR GARNISH)	10	2.20	22.00	25.00	16.50	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE BOARD , HANDLE PULL	1	19.50	19.50	25.00	14.63	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	118.20	25.00	88.65	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE STAY ASSY , BACK DOOR , RH	1	235.00	235.00	25.00	176.25	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE BOLT, BACK DOOR STAY , RH & LH	2	11.80	23.60	25.00	17.70	Replace	0	0	Not Give	Xan
Standard	Main	BODY LH		TAIL GATE STAY BRACKET, BACK DOOR , RH & LH	1	11.80	11.80	25.00	8.85	Replace	0	0	Not Give	Xan

Total Spare Part Cost 12,293.58

Surveyor Total 5,097.77

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 0

Surveyor Approval

SMRT Recommendation

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	S.No.
Standard	Main			TAIL GATE STAY ASSY, BACK DOOR, LH	1	235.00	235.00	25.00	176.25	Replace	0	0	Not Give	✓	Xan
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	0	0	Not Give	✓	Xan
Standard	Main			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	0	0	Not Give	✓	Xan
Standard	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	✓	Xan
Standard	Main			CLAMP SUB-ASSY, BATTERY	1	41.40	41.40	25.00	31.05	Replace	0	0	Not Give	✓	Xan
Standard	Main			CLAMP, BATTERY, NO.2	1	43.30	43.30	25.00	32.47	Replace	0	0	Not Give	✓	Xan
Standard	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	✓	me /
Standard	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	991.5	Replace	✓	me /
Standard	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	0	0	Not Give	✓	Xan
Standard	Main			PROTECTOR, REAR SPOILER	2	14.00	28.00	25.00	21.00	Replace	0	0	Check	✓	?
Standard	Main			WIRE, TAIL GATE BACK DOOR	1	246.80	246.80	10.00	222.12	Replace	0	0	Not Give	✓	Xan
Standard	Main			WIRE, TAIL GATE BACK DOOR, NO.2	1	246.80	246.80	10.00	222.12	Replace	0	0	Not Give	✓	Xan
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓	me /
Standard	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓	me /
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	472.3	Replace	✓	me /
Standard	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Not Give	✓	Xan
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓	me /
Standard	Main			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	1	52.70	52.70	25.00	39.53	Replace	1	39.53	Replace	✓	me /
Standard	Main			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	1	52.70	52.70	25.00	39.53	Replace	1	39.53	Replace	✓	me /
Standard	Main			MOULDING SUB-ASSY, ROOF TOP	1	637.40	637.40	25.00	478.05	Replace	1	478.0	Replace	✓	me /

Total Spare Part Cost 12,293.58

Surveyor Total 5,097.77

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 0

Final Spare Part Cost 9,452.42

Final Sur Total 5,097.77

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	600	
Total:			1,690.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0 X11	
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY TAIL GATE	378.00	200	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:			1,296.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X11	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0 X11	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	475.00	125	
7	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	60	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0 X11	
Total:			1,435.00	305.00	

Summary

Estimator Assesment(\$)

Surveyor Assesment(\$)

Surveyor Assessment(\$)

	Estimator Assessment(\$)	
Total Spare Part Detail	9,452.42	5,097.77
Total Labour Cost	1,690.00	600.00
Total Spray Painting	1,296.00	600.00
Other	1,435.00	305.00
Overall Total	13,873.42	6,602.77
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	13,850.00	6,600.00
Surveyor Approved Amount		6,600.00
No of Repair Days*	8	6

Remarks

resurvey after repair / lump sum repair

Surveyor Name

Rasul

Signature



Save

Clear

Survey Date

03/08/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/08/2022 13:55 (SGT)
Reported by	Driver
Date of Accident	03/08/2022 11:23 (SGT)
Exact Location of Accident	Paterson Rd, Singapore
Additional Location Information	PATERSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6320X
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	WU CHING HUNG
NRIC No	SXXXX504A
Date Of Birth	07/03/1952
Occupation	Outdoor

Date Of Driving Pass	31/07/2006
Driving experience	16 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	5
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN CHILD
Gender	Male

PASSENGER 4

Name	UNKNOWN CHILD
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS STATIONARY ALONG PATERSON ROAD WITH FOUR PASSENGERS (COUPLE /2 CHILDREN MALE AND FEMALE) ON BOARD AS IT WAS THE RED TRAFFIC LIGHT. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE YP7842K HAD COLLIDED ONTO THE REAR OF MY TAXI AND THE IMPACT PUSHED MY TAXI FORWARD.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7842K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	ADAIKALAM RAJA
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**).

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reducing Centre Personnel
(Name as in NRIC/D card)

Sketch Plan


		Paterson Road A - SHD6320X B - YP7542K
--	--	--

Describe Circumstance of the Accident

Declaration

(We declare the foregoing particulars are true in every respect)


Police Officer's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Officer (Personnel)
(Name as on NRIC ID card)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6320X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS100364
Chassis No.:	JTDKB3FU303573374
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count: -	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$13,603.00
Total Rebate Amount:	\$17,353.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Aug 2022

OK