



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2301581
3 ANSON ROAD #16-00	INV Date	16/03/2023
SPRINGLEAF TOWER	Reference	CC6/CTI22007416/Kpa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SBU 5807Y
Insured Veh.	XE 750H
Claim No.	SNM22D205379/C02
Policy No.	DMCVSNW00060082204
Accident Date	30/07/2022
Inspection Date	30/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22007416/Kpa3q2 Date: 16/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 750H	Veh. Inspected	SBU 5807Y
Policy No.	DMCVSNW00060082204	Coverage (\$)	0.00
Claim No.	SNM22D205379/C02	Excess (\$)	0.00
Assign From		Assign Date	30/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104539988	Colour	WHITE
Odometer	33311 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/07/2022	Inspection Date	30/08/2022
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 5807Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH FRONT DOOR	BENT	1,121.08	1,121.08
1	RH FRONT DOOR GARNISH (VERTICAL)	NECESSARY	84.78	84.78
1	RH FRONT DOOR BLACK TAPE	NECESSARY	78.93	78.93
1	RH FRONT FENDER	BENT	540.76	540.76
1	RH FRONT FENDER EMBLEM VVTI	NECESSARY	48.33	48.33
1	RH SIDE MIRROR ASSY	CRACKED	988.73	988.73
1	SPORTS RIM -16	SERVICEABLE	2,173.50	-
	LESS 25% DISCOUNT		-1,259.03	-715.65
			3,777.08	2,146.96
LABOUR				
	TO TRANSFER RH FRONT DOOR MECHANISM.		100.00	60.00
	TO TRANSFER TYRE TO NEW RIM AND BALANCING.	NOT NECESSARY	50.00	-
	COMPUTERISE WHEEL ALIGNMNET.	NOT NECESSARY	120.00	-
	TO REPAIR RH REAR DOOR INCLUDING REPLACEMENT OF PARTS.		500.00	400.00
	TO SPRAY PAINT ON RH FRONT FENDER ,RH FRONT DOOR ,RH REAR DOOR ,RH ROCKER PANEL ,RH SIDE MIRROR.		1,100.00	720.00
			1,870.00	1,180.00
GRAND TOTAL			5,647.08	3,326.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CC6/CTI22007416/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBU 5807Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBU 5807Y

RE-INSPECTION

