



FALCON - AIR

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

CHEN JINGYA
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
MARK OOI - 82838589

Attention : Motor Claim Department
Contact : 84396894

*Not authorized
1/1 Day &
Resurvey After 4 days*

Estimate : ES012426

Date : 02/08/2022
Vehicle Num. : SBU 5807Y
Make/Model : TOYOTA ALTIS CLASSIC CVT-2015
Chassis/Eng# : MR053REH104539988
Accident Date : 30/07/2022
Claim No. :
Reference : TP - MSIG AGT CHINA TAIPING
Policy No. : A300506344 QMX

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	RH FRONT DOOR	<i>By</i> 1,121.08	<i>✓</i>
2.	1 PC	RH FRONT DOOR GARNISH (VERTICAL)	<i>By</i> 84.78	<i>✓</i>
3.	1 PC	RH FRONT DOOR BLACK TAPE	<i>By</i> 78.93	<i>✓</i>
4.	1 PC	RH FRONT FENDER	<i>By</i> 540.76	<i>✓</i>
5.	1 PC	RH FRONT FENDER EMBLEM VVTI	<i>By</i> 48.33	<i>✓</i>
6.	1 PC	RH SIDE MIRROR ASSY	<i>By</i> 988.73	<i>✓</i>
7.	1 PC	SPORTS RIM - 16'	<i>By</i> 2,173.50	<i>X</i>
List Total S\$:			5,036.11	
25.00% Discount S\$:			1,259.03	
			<u>3,777.08</u>	

LABOUR :	Amount S\$	Notes
TO TRANSFER RH FRONT DOOR MECHANISM	100.00	<i>600</i>
TO TRANSFER TYRE TO NEW RIM AND BALANCING	<i>By</i> 50.00	<i>X</i>
COMPUTERISE WHEEL ALIGNMENT	<i>By</i> 120.00	<i>X</i>
TO REPAIR RH REAR DOOR INCLUDING REPLACEMENT OF PARTS	500.00	<i>400</i>
TO SPRAY PAINT ON RH FRONT FENDER, RH FRONT DOOR, RH REAR DOOR, RH ROCKER PANEL, RH SIDE MIRROR	1,100.00	<i>720</i>
Labour Total S\$:	<u>1,870.00</u>	

E. & O.E. Total S\$: 5,647.08

FALCON AIR AUTO SERVICES PTE LTD

Estimate was prepared from visual inspection. Further materials and labour charges may be required when repair is completed. We will advise you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)