

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNA4356B/2208102

03<sup>th</sup> August 2022

The Manager  
Motor Claim Department  
AIG Asia Pacific Insurance Pte Ltd  
CHARTIS Building  
78 Shenton Way #07-16  
Singapore 079120

Date Of Accident : 02<sup>nd</sup> August 2022  
Location : ECP towards City  
Third Party Claim Vehicle No : SLE 6012 H  
Repair Cost for Vehicle No : SNA 4356 B BMW 318i

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia <i>DD</i>	1	1,184.55	\$ 1,184.55 <del>---</del>
2	Rear bumper clips <i>see</i>	1set	30.00	\$ 30.00 <del>---</del>
3	Rear bumper reflector LH <i>11</i>	1	48.30	\$ 48.30 <del>X</del>
4	Rear bumper sensor <i>shurf</i>	2	280.95	\$ 561.90 ✓
5	Rear bumper sponge <i>NF</i>	1	73.55	\$ 73.55 <del>X</del>
6	Rear bumper sponge centre <i>NF</i>	1	175.80	\$ 175.80 <del>X</del>
7	Rear bumper reinforcement <i>BMW</i>	1	477.30	\$ 477.30 <del>X</del>
8	Rear bumper side retainer LH <i>11</i>	1	185.80	\$ 185.80 <del>X</del>
9	Rear bumper exhaust silencer assy <i>R</i>	1	1,040.70	\$ 1,040.70 <del>X</del>
10	Rear bumper exhaust clamping bush <i>11</i>	1	80.70	\$ 80.70 <del>X</del>
11	Rear end panel <i>R</i>	1	622.95	\$ 622.95 <del>X</del>
12	Rear end panel sealer (s/nett) <i>11</i>	1	80.00	\$ 80.00 <del>X</del>
				\$ 4,561.55

(52)

*Not Allowed  
due  
8/8/22  
2/S #2700/  
3 days  
When photo attached*

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNA4356B/2208102

03<sup>th</sup> August 2022

Balance b/f		\$ 4,561.55	
<b><u>Labour Charges :-</u></b>			<b><u>Amounts</u></b>
Cut out, renew, knocking & welding rear end panel, remove & install all damage parts, straighten & re-align body		\$ 880.00	400
Tuff-kote on damage parts	11	\$ 40.00	X
Spray painting on damage parts		\$ 680.00	400
Remove & refix rear exhaust silencer assy	11	\$ 100.00	X
Remove & refix rear bumper sensor		\$ 100.00	50
Check all lighting after repairs		\$ 35.00	20
Diagnostic & reset	11	\$ 300.00	X
		\$ 2,135.00	
Labour Charge		\$ 2,135.00	
Total Amount		\$ 6,696.55	

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P- 2669.39  
52  
2535.92  
870  
3405.92  
202  
2724

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNA4356B/2208102

25<sup>th</sup> August 2022

The Manager  
Motor Claim Department  
AIG Asia Pacific Insurance Pte Ltd  
CHARTIS Building  
78 Shenton Way #07-16  
Singapore 079120

Date Of Accident : 02<sup>nd</sup> August 2022  
Location : ECP towards City  
Third Party Claim Vehicle No : SLE 6012 H  
Repair Cost for Vehicle No : SNA 4356 B BMW 318i

## Supplementary of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper moulding(black) <i>cu7</i>	1	105.64	\$ 105.64
2	Rear bumper guide centre <i>cm</i>	1	211.30	\$ 211.30
3	External antenna <i>cu</i>	1	98.70	\$ 98.70
				<hr/>
				\$ 415.64

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.