

ASS. REC. BY: Taught

REF:

CC4/ALS 22007420/T993

ASSIGNMENT

OE 2032 Jan

2012 Jan

From: _____ Date: _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 938K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBF 9048Z Yr Regn: 2012 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Harley Davidson PLSTF Fatboy C.C. 1690Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SHD1 Bxv C2CB 01 4793Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Rib / S/Rim / STD A/Rim orTyre Size: F: 140/70R17R: 200/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 4/8/22Survey held at SingaporeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Rep. Format: _____

Lump Sum / L.B.L. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL



ASSESSMENT FOR REPAIR : FBF9048Z
HARLEY DAVIDSON FLSTF FATBOY
COE EXPIRY : 08 Jan 2032

Lump Sum / Part by Part ☒

Qty	Description
1	REAR FENDER <i>ib</i> ✓
1	REAR BRAKE LIGHT <i>Cna</i> ✓

Repairer's Estimate	1st Survey	Repair Survey	Final Survey
2,600.00			
380.00			

2,980.00

Special Nett Items

STEERING CONE & BEARING
 FRONT FORK ALIGNMENT
 WHEEL ALIGNMENT *7.60 photo*
 FRAME ALIGNMENT *100? photo*
 SIDE BOX L&R SET *into*

120.00		
200.00		
2,800.00		

3,120.00

Total Parts

6,100.00

Labour Charges

- 1 Workmanship to renew damage parts & areas

350.00
 350.00

200

Total Parts & Labours Concluded

6,450.00

Taufik 99495749 / 62563561
'wp' 4/8/22 @ 1030 am
Resurvey new parts
Taufik @ lkk auto.com
03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com