

TP A16.
Asher.

SML6462T. 2019 May.
Honda Vezel 1496 cc
RU11315660.

Rear Bumper.	Del'd	745.90	✓
Rear Bumper Clips.	in	30(SN)	✓
Rear Bumper Side Holder RH	Del'd	32.90	✓
Rear Bumper Reflector RH.	could	141.10	✓
Trillup RH.	could	495.20	✓
Trillup lower Apron RH.	Dist'd	195.10	✓
Rear RH Fender	Dist'd	984.40	✓
Rear RH Fender Inner Shield	Del'd	168.90	✓
Rear RH Fender Inner Shield clips.	in	30(SN)	✓
Rear RH Fender Arc Garnish.	Dist'd	205.20	✓
Rear RH Fender Arc Garnish clips.	in	20(SN)	✓
Rear RH Fender Air Vent	Del'd	96.50	✓
Rear RH Fender Inner Trim	Del'd	305.40	✓
Rear RH Fender Inner Trim clips.	in	30(SN)	✓
Rear RH Door.	Rep's	1108.20	✗

SML 6462T.

Rees End Panel. Repair	585.40. ✓
Rees RH Wheel Rim. Cut	700(SN) 500(SN)
Rees RH Tyre. Run down	280(SN) 180(SN)
Rees Axle Bent	1513.20. ✓
Rees RH Shock Absorber Rnd	330.90 ✓
Rees RH Wheel Hub c/w Bearings. Rnd	363.90. ✓
Rees Exhaust Pipe. Dented	645.70 ✓
Roof Air Bag RH.	1588.10. ✓
Roof Air Bag Sensor.	240.40. ✓
Driver Seat Air Bag.	Activated 1041.40 ✓
Driver Seat Air Bag Sensor	230.50. ✓
Front Seat Belt x 02	698.6 x 2 = 1397.20 ✓
Roof Inner Trim Board Torn	1050.20 ✓
Roof Inner Trim Board clips.	50(SN) ✓
Air Bag ECU. Activated	982.40. ✓
Driver Seat Cushion. 850(SN). Torn	12736.60 S.N. 1520
	16189.28

SML6462T.

Panel Beating

~~1200~~ 800

Spray Painting.

~~1200~~ 800

Wiring

~~100~~ 30

To spray tuff coat.

~~150~~ 80

To remove upholstery.

~~150~~ 80

To remove reverse sensor

~~100~~ 50

To transfer rear door fittings.

150 X

To remove rear undercarriage.

~~380~~ 320

To perform wheel alignment.

~~150~~ 80

To remove roof inner trim board.

~~255~~ 150

To remove air bags.

~~450~~ 350

To remove seat belts.

~~200~~ 150

To remove driver seat cushion.

~~200~~ 100

To reset air bag settings

~~400~~ 300

2890 3290

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 14999.28

H/S: 12K

12 Days.

12000