

Not Authorized
 del
 2/5 #4350/
 4 days
 Whighe Atkinson



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
 Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : GBG2141C
 Date of Accident : 02 August 2022

Mr Wong Chin Yen (Wang Zhenyan)

Date : 03 August 2022

Estimate To Repair SKD3021T - Toyota WISH 1.8 CVT
 Chassis No : JTDGG20W405002167

L66 - Marcus

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>no/sent</i>	\$ 1,415.50
02	1 pc	tailgate lid centre logo <i>del</i>	\$ 50.80
03	1 pc	tailgate lid outer chrome garnish <i>one</i>	\$ 398.90
04	1 pc	tailgate lid inner trimboard <i>see</i>	\$ 348.80
05	1 pc	tailgate lid inner lock <i>no/sent</i>	\$ 470.40
06	1 pc	tailgate lid inner lock weatherstrip <i>tw</i>	\$ 322.30
07	1 pc	rear windscreen weatherstrip moulding <i>see</i>	\$ 180.00
08	1 pc	o/s rear lamp <i>11</i>	\$ 638.20
09	6 ps	o/s rear lamp clips @ \$4.50 <i>11</i>	\$ 27.00
10	1 pc	rear bumper <i>del/sent</i>	\$ 518.70
11	2 ps	rear bumper bracket @ \$51.00 <i>2</i>	\$ 102.00
12	2 ps	rear bumper side retainer @ \$48.80 <i>see</i>	\$ 97.60
13	8 ps	rear bumper fastener clips @ \$4.50 <i>see</i>	\$ 36.00
14	1 pc	rear end panel <i>no/sent</i>	\$ 515.10
15	1 pc	rear end panel inner trim <i>tw</i>	\$ 292.00
16	8 ps	rear end panel inner trim clips @ \$4.50 <i>11</i>	\$ 36.00
17	1 pc	rear exhaust box <i>2</i>	\$ 780.00
	1 pc	Rear antenna sensor <i>one</i>	\$ 241.50
		Less 25 %	\$ 1,484.33
			\$ 4,452.98
<u>SPECIAL NETT ITEMS</u>			
18	1 set	rear bumper parking sensor <i>shut</i>	\$ 0.00
19	0 pc	rear licence plate <i>sent</i>	\$ 0.00
20	1 pc	rear windscreen sealant <i>see</i>	\$ 50.00
21	1 pc	rear windscreen inner sponge seal <i>see</i>	\$ 40.00
			\$ 90.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 40.00
02		To reinstall of rear bumper parking sensor.	\$ 50.00
03		To remove and refit rear windscreen glass.	\$ 120.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 100.00
06		To repair and realign rear exhaust box.	\$ 80.00
07		To rust-proofing of the affected areas.	\$ 80.00
08		Putty and spray painting of the affected portion.	\$ 1,000.00

Handwritten marks and checkmarks in the right margin of the table, including 'X', '✓', and numerical annotations like '20', '60', '800'.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : GBG2141C
Date of Accident : 02 August 2022

Mr Wong Chin Yen (Wang Zhenyan)

Date : 03 August 2022

Estimate To Repair SKD3021T - Toyota WISH 1.8 CVT
Chassis No : JTDGG20W405002167

S/No	Quantity	Description	Amount
09		<u>LABOUR & MISC. CHARGES</u> Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,100.00
			\$ 2,670.00
		Total	\$ 7,212.98

620

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 4450.40
252
3337.80
320
1790
5447.80
202
4258