



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207129

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/11/2022
Reference CC6/CTI22007429/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLG 852D
Insured Veh. SLN 2256A
Claim No. SNM22D205382/C02
Policy No. DMPCSNW00232652104
Accident Date 31/07/2022
Inspection Date 01/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22007429/Apa3q2 Date: 18/11/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 2256A	Veh. Inspected	SLG 852D	
Policy No.	DMPCSNW00232652104	Coverage (\$)	0.00	
Claim No.	SNM22D205382/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31211039	Colour	WHITE	
Odometer	126389 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/65 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/65 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/65 R16	YOKOHAMA	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	31/07/2022	Inspection Date	01/08/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 852D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	DENTED	1,298.00	1,100.00
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	386.00	285.00
2	REAR TAILGATE LAMP @\$398.00	CRACKED	796.00	796.00
1	REAR TAILGATE WINDSCREEN GLASS MOULDING	NECESSARY	178.00	178.00
1	REAR TAILGATE OUTER GARNISH	CRACKED	322.00	322.00
1	REAR TAILGATE INNER HANDLER	NOT NECESSARY	69.00	-
1	REAR TAILGATE LOCK	DAMAGED	312.00	255.00
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	24.00	-
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	56.00	56.00
1	REAR TAILGATE EMBLEM VEZEL	NECESSARY	56.00	56.00
1	REAR TAILGATE EMBLEM HYBRID	NECESSARY	68.00	68.00
1	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	511.00	-
1	REAR TAILGATE WIPER ARM	NOT NECESSARY	56.00	-
1	REAR TAILGATE WIPER BLADE	NOT NECESSARY	34.00	-
1	REAR TAILGATE WEATHER STRIPE	CUT	187.00	187.00
2	REAR TAILGATE STOPPER @\$18.00	NOT NECESSARY	36.00	-
1	REAR TAILGATE KEYLESS SENSOR	NOT NECESSARY	332.00	-
2	REAR TAILLAMP @\$597.00	CRACKED	1,194.00	990.00
2	REAR TAILLAMP LOWER BRACKET @\$32.00	NOT NECESSARY	65.00	-
2	REAR TAILLAMP SIDE GARNISH @\$42.00	NOT NECESSARY	84.00	-
1	REAR BUMPER	DEFORMED	859.00	745.00
2	REAR BUMPER SIDE @\$452.00	DEFORMED	904.00	390.00
2	REAR BUMPER SIDE RETAINER @\$55.00	NECESSARY	110.00	70.00
2	REAR BUMPER REFLECTOR @\$187.00	NOT NECESSARY	374.00	-
2	REAR FENDER INNER COWLING @\$199.00	NOT NECESSARY	398.00	-
2	REAR FENDER INNER TRIM BOARD @\$529.00	N/S CRACKED	1,058.00	325.00
1	REAR END PANEL	DENTED	620.00	545.00
1	REAR END PANEL TOP GARNISH	DEFORMED	381.00	245.00
1	REAR FLOOR PANEL	NOT NECESSARY	1,498.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	296.00	-
1	REAR FLOOR PANEL TOOLS BOX GARNISH	NOT NECESSARY	425.00	-

Report Ref No. CC6/CTI22007429/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL UNDER COVER	NOT NECESSARY	264.00	-
	LESS 20% DISCOUNT		-2,650.20	-1,322.60
			10,600.80	5,290.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	60.00	10.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR TAILGATE CAMERA (SN)	NOT NECESSARY	380.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
			1,050.00	300.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		1,800.00	600.00
	LABOUR FOR SPRAYPAINTING.		1,600.00	600.00
	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING.		300.00	60.00
	WIRING CHECK.		80.00	30.00
	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS.		200.00	60.00
	LABOUR FOR REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS.		150.00	120.00
	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY / CARPET / INNER TRIM.		300.00	60.00
	LABOUR FOR REMOVE & TEST REAR HYBRID BATTERY.	NOT NECESSARY	480.00	-
			4,910.00	1,530.00
GRAND TOTAL			16,560.80	7,120.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CC6/CTI22007429/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 852D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 852D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

