

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Xiao Tang

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 575.00	\$ 575.00
2	BOOT LID LOGO	1	\$ 70.00	\$ 70.00
3	BOOT LID EMBLEM 'VIOS' <i>2 pc</i>	1	\$ 65.00	\$ 65.00
4	BOOT LID EMBLEM 'E'	1	\$ 55.00	\$ 55.00
5	BOOT LID OUTER MOULDING <i>Dented</i>	1	\$ 190.00	\$ 190.00
6	BOOT LID NUMBER PLATE LAMP <i>new</i>	2	\$ 42.00	\$ 84.00
7	BOOT LID TOP LOCK <i>Dented</i>	1	\$ 155.00	\$ 155.00
8	BOOT LID LOWER LOCK new NEC	1	\$ 25.00	\$ 25.00
9	BOOT LID KEY LOCK <i>new</i>	1	\$ 225.00	\$ 225.00
10	BOOT LID WEATHER STRIP <i>lt</i>	1	\$ 205.00	\$ 205.00
11	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
12	REAR BUMPER <i>Dented</i>	1	\$ 495.00	\$ 495.00
13	REAR BUMPER REFLECTOR <i>RH dented</i>	2	\$ 105.00	\$ 210.00
14	REAR BUMPER BRACKET <i>LH Dented</i>	2	\$ 89.00	\$ 178.00
15	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 105.00	\$ 210.00
16	REAR BUMPER SIDE RETAINER (REAR) <i>2yd</i>	2	\$ 55.00	\$ 110.00
17	TAIL LAMP <i>crushed</i>	2	\$ 345.00	\$ 690.00
18	TAIL LAMP PANEL <i>RH Dented</i>	2	\$ 190.00	\$ 380.00
19	REAR FENDER <i>RH Buckled</i>	2	\$ 915.40	\$ 1,830.80
20	REAR FENDER INNER COWLING <i>new</i>	2	\$ 175.00	\$ 350.00
21	REAR FENDER INNER TRIM <i>RH crumpled</i>	2	\$ 295.00	\$ 590.00
22	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 90.40	\$ 90.40
23	REAR CHASSIS MEMBER RH <i>Ry's</i>	1	\$ 694.30	\$ 694.30
24	REAR END PANEL <i>Dented</i>	1	\$ 439.00	\$ 439.00
25	REAR END PANEL TOP GARNISH <i>deformed</i>	1	\$ 230.00	\$ 230.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLJ2232P**
 MODEL : **TOYOTA VIOS**
 DATE OF ACCIDENT : 29.07.2022
 TIME OF ACCIDENT : 16:40HRS

26	REAR FLOOR PANEL TOP BOARD <i>form</i>	1	\$ 175.00	\$ 175.00	✓
27	REAR FLOOR PANEL TOP SPONGE (SIDE) <i>Rehd</i>	2	\$ 275.00	\$ 550.00	✓
28	CENTER EXHAUST <i>new</i>	1	\$ 3,100.00	\$ 3,100.00	+
29	CENTER EXHAUST INSULATOR <i>3af</i>	1	\$ 95.00	\$ 95.00	+
30	CENTER EXHAUST GASKET (SET) <i>1m</i>	1	\$ 60.00	\$ 60.00	+
31	REAR EXHAUST MOUNTING <i>3af</i>	4	\$ 45.00	\$ 180.00	+
32	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+
33	REAR EXHAUST INSULATOR <i>new</i>	1	\$ 89.00	\$ 89.00	+
34	REAR EXHAUST PIPE WITH BOX <i>But</i>	1	\$ 690.00	\$ 690.00	✓
<i>Rear Floor Panel</i>			<i>1</i>	<i>840</i>	<i>840</i>
<i>Bruchd</i>			<i>7243.80</i>	<i>5432.85</i>	
			TOTAL PRICE	\$ 13,285.50	
			LESS 25%	\$ 3,321.38	
			SUB TOTAL PRICE	\$ 9,964.13	

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>m</i>	1	\$ 50.00	\$ 50.00	30.
3	BOOT LID OUTER MOULDING CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	✓
4	BOOT LID EMBLEM 'SPORT' <i>m</i>	1	\$ 80.00	\$ 80.00	50.
5	REAR WINDSCREEN INNER SEAL <i>3m</i>	1	\$ 60.00	\$ 60.00	30
6	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	40.
7	REAR SPOILER <i>Distorted new</i>	1	\$ 850.00	\$ 850.00	500 +
8	REAR FENDER SEALANT <i>m</i>	2	\$ 150.00	\$ 300.00	60.
9	REAR FENDER INNER COWLING CLIPS (SET) <i>m</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER INNER TRIM CLIPS (SET) <i>m</i>	1	\$ 80.00	\$ 80.00	30
11	TAIL LAMP CLIPS (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	✓
12	REAR DIFFUSER <i>Distorted</i>	1	\$ 1,000.00	\$ 1,000.00	600
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	10
14	REAR END PANEL INSULATION SEAL <i>m</i>	1	\$ 150.00	\$ 150.00	60.
15	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>But</i>	1	\$ 250.00	\$ 250.00	120
16	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+
17	REVERSE SENSOR <i>Distorted</i>	1	\$ 220.00	\$ 220.00	20.

1260

TOTAL \$ 3,790.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS	\$ 2,200.00	<i>1200</i> 1600
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS	\$ 1,800.00	<i>1200</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLJ2232P**
 MODEL : **TOYOTA VIOS**
 DATE OF ACCIDENT : 29.07.2022
 TIME OF ACCIDENT : 16:40HRS

3	TUFF COAT	\$	250.00	60
4	WIRING/ BULB CHECKING	\$	80.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$	200.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$	80.00	50
8	REMOVE & REFIX REAR WINDSCREEN	\$	120.00	✓
9	REMOVE AND REFIX REAR EXHAUST	\$	180.00	80
10	TRANSFER BOOT LID MECHANISM	\$	80.00	60
11	REMOVE AND REFIX REAR SPOILER AND DIFFUSER	\$	300.00	x
12	TO CONDUCT WATER LEAKAGE TEST	\$	80.00	x
13	REAR CHASSIS MEMBER ALIGHMENT	\$	250.00	x
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	x

TOTAL \$ 5,880.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,754.13
 TOTAL LABOUR COST : \$ 5,880.00
 TOTAL REPAIR COST : \$ 19,634.13

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
 2/5 01/08/22
 09 Days.

total: 10002.85

2/5 : 5.9K (Nett Value)

3310