

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 05 Aug 2022

Preliminary Advice

Vehicle No	: SMM6867D	Accident Date	: 01/08/2022
Make	: SUBARU XV	Policy No.	: SP2000593898- 01
Assignment Date	: 03/08/2022	Excess	: S\$2,000.00
Date of Inspection	: 04/08/2022	Est. Duration of Repair	: 7
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,348.90
Revised Amount	:S\$	7,043.10
Check Items (Estimated)	:S\$	1,642.30
Total	:S\$	8,685.40

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 37,000.00
COE / PARF Rebate	:S\$ 21,690.00

Salvage Value	:S\$
Margin for Repair	:S\$ 15,310.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.