



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22007439/Acy3m4 Date: 19/08/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6391B	Veh. Inspected	SLF 282D	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026093	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	04/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ACR507129296	Colour	BLACK	
Odometer	138554 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	TOYO	6 mm	
L/H Front Tyre	225/50 R18	TOYO	6 mm	
R/H Rear Tyre	225/50 R18	TOYO	6 mm	
L/H Rear Tyre	225/50 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/07/2022	Inspection Date	04/08/2022	
Survey held at	MIRAGE MOTORWERKZ PTE LTD 10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	