

MIRAGE MOTORWERKZ PTE LTD

Main Branch

10 Kaki Bukit Road 2
#01-28 /29 First East Centre
Singapore 417868
+65 6635 7111 +65 6635 7112

East Coast Branch

Shell Autoserv @ Siglap
40 Upper East Coast Road
Singapore 455212
+65 6977 7117

 admiral@mirage.mil.tr

 www.marathon.sg

 www.facebook.com/TeamMunagi

2/8/2022

ESTIMATED REPAIR CHECKLIST

TO : ATTENTION : MOTOR INSURANCE CLAIM CLAIM TYPE : 3RD PARTY CLAIM ACCIDENT DATE/TIME :	VEHICLE REGISTRATION NO.: SLF282D VEHICLE MAKE/MODEL: TOYOTA / ESTIMA CHASSIS NUMBER: ACR507129296 CONTACT PERSON :	JP Lopez celine
---	--	--------------------

PARTS		QTY	PER UNIT	PRICES
1	FRONT BUMPER <i>Distalad</i>	1	\$ 981.60	\$ 981.60
2	FRONT BUMPER SIDE HOLDER RH <i>and</i>	1	\$ 88.60	\$ 88.60
3	FRONT BUMPER FOG LAMP RH <i>Missing</i>	1	\$ 356.90	\$ 356.90
4	FRONT BUMPER FOG LAMP COVER RH	1	\$ 141.60	\$ 141.60
5	FRONT BUMPER SPONGE <i>could</i>	1	\$ 163.80	\$ 163.80
6	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 415.40	\$ 415.40
7	FRONT BUMPER LOWER GRILLE <i>could</i>	1	\$ 241.90	\$ 241.90
8	FRONT GRILLE <i>could</i>	1	\$ 587.30	\$ 587.30
9	FRONT GRILLE LOGO <i>over</i>	1	\$ 85.90	\$ 85.90
10	HEADLAMP RH <i>could</i>	2	\$ 2,479.90	\$ 4,959.80
11	BONNET <i>Distalad</i>	1	\$ 1,021.60	\$ 1,021.60
12	FRONT RH FENDER <i>Distalad</i>	1	\$ 685.90	\$ 685.90
13	FRONT RH FENDER INNER SHIELD <i>for</i>	1	\$ 235.90	\$ 235.90
14	FRONT RH FENDER GLASS <i>shutter</i>	1	\$ 545.90	\$ 545.90
15	FRONT RH WING MIRROR <i>and</i>	1	\$ 1,160.70	\$ 1,160.70
16	FRONT RH WING MIRROR COVER <i>Missing</i>	1	\$ 95.60	\$ 95.60
17	FRONT RH WINDSCREEN PILLAR <i>Repair</i>	1	\$ 895.60	\$ 895.60
18	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 245.90	\$ 245.90
19	FRONT RH LOWER ARM <i>Dist</i>	1	\$ 532.40	\$ 532.40
20	FRONT RH SHOCK ABSORBER <i>new</i>	1	\$ 372.50	\$ 372.50
21	FRONT RH KNUCKLE ARM <i>new</i>	1	\$ 581.60	\$ 581.60
22	FRONT RH WHEEL HUB C/W BEARING <i>and</i>	1	\$ 412.90	\$ 412.90
			Sub total	SUBTOTAL :
			Less 25%	\$ 13,382.20
			Total List	LESS 25% :
				\$ 2,470.17
				PARTS TOTAL : \$ 10,912.03

SPECIAL NETT	QTY	PER UNIT	PRICES
1 FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2 FRONT GRILLE CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
3 FRONT RH FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4 FRONT RH FENDER GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
5 FRONT WINDSCREEN SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
6 FRONT RH TYRE <i>new</i>	1	\$ 300.00	\$ 300.00
7 FRONT RH WHEEL RIM <i>new</i>	1	\$ 1,000.00	\$ 1,000.00
8 TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
9 REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00
Sub total		S/N TOTAL :	\$ 1,650.00

LABOUR CHARGES		PRICES	ADJUSTMENT
1	PANEL BEATING	\$ 1,200.00	703
2	SPRAY PAINTING	\$ 1,000.00	700
3	WIRING	\$ 50.00	30
4	TO SPRAY TUFF COAT	\$ 150.00	40
5	TO REMOVE FRONT WINDSCREEN	\$ 180.00	X
6	TO REMOVE DASHBOARD	\$ 350.00	X
7	TO DISMANTLE FRONT UNDERCARRIAGE	\$ 320.00	120
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80
		\$ 3,400.00	

1670

LKK Auto Consultants hence notify the Repairer of the following:

- to resurvey before/after spray painting
- to display damaged part(s) during resurvey

LKK Auto Consultants hence notify
the Repairer of the following:

LABOR TOTAL:

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL: 12460.53

Adrian L
r/s 04/08/2
06 days
total: 9763.80
L/S: 7.81K

MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44

Premier @ Kaki Bukit

Singapore 415875

Phone Number: 69777077

Fax Number: 69777080

Customer:		Date:	4/8/2022 10:52 AM
Company:	MIRAGE	VIN	SLF282D
License NO:		Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

TOYOTA-RV,VAN, ESTIMA Hybrid AHR20W (From S/N:7000101), 14-18 (Customized)

Primary Angles

			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	5°05'	6°35'	----
		Right	----	5°05'	6°35'	----
	Camber	Left	0°06'	-1°00'	0°30'	0°06'
		Right	-0°36'	-1°00'	0°30'	-0°36'
	Toe	Left	-0°12'	-0°02'	0°08'	-0°12'
		Right	2°42'	-0°02'	0°08'	2°42'
		Total	2°30'	-0°05'	0°15'	2°30'
Rear	Camber	Left	-1°36'	-2°00'	-1°00'	-1°36'
		Right	-1°30'	-2°00'	-1°00'	-1°30'
	Toe	Left	0°06'	-0°05'	0°15'	0°06'
		Right	0°18'	-0°05'	0°15'	0°18'
		Total	0°24'	-0°10'	0°30'	0°24'
	Thrust Angle		0°06'	----		0°06'

Secondary Angles

			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	11°25'	11°25'	----
	Right		----	11°25'	11°25'	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-0.1"	----	----	-0.1"
	Rear		-0.4"	----	----	-0.4"
Track Width Diff.			0.4"			0.4"
Wheel Base Diff.			0.2"			0.2"
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----