

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 62759
Date Estimated : 02/08/2022
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Aw Teck Kay Bobbin (Hu Dejia Bobbin
88 Telok Blangah Heights
#07-353

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 100088

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR8080D	WBAJG120503G76722	30/11/2018	X1 sDrive18i	39018

DESCRIPTION	VALUE
To replace rear bumper and tailgate	1700 ✓ 3,400.00
To respray rear bumper and tailgate.	1972 ✓ 2,076.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 ✓ 177.00
To replace tail light.	X 481.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	504 ✓ 531.00
To replace rear windscreen glass.	545 ✓ 574.00
To conduct water leak tests.	71 ✓ 75.00
To supply and install rear windscreen solar film.	504 X 531.00
To check electrical wiring system and lighting at the rear section for proper function.	168 ✓ 177.00
Sundries.	150.00 ✓

Total Labour 1: **8,172.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,298.95	1,298.95 ✓
REAR LH BUMPER MOUNT	1	166.90	166.90
REAR RH BUMPER MOUNT	1	166.90	166.90
RR BUMPER CARRIER	1	523.75	523.75
REAR BUMPER TRIM PANEL BOTTOM (BASI	1	208.45	208.45 ✓
MOUNTING SMART OPENER	1	47.00	47.00
RR BUMPER LH CORNER MOUNTING	1	147.50	147.50

