



Final Report

Estimate No. : **b1 62759**
Date Estimated : 02/08/2022
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -

Aw Teck Kay Bobbin (Hu Dejia Bobbin
88 Telok Blangah Heights
#07-353

Singapore 100088

- ACCOUNT - **135**

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLR8080D	WBAJG120503G76722	30/11/2018	X1 sDrive18i	39018

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, boot lid and attachments include knocking out dents caused by the accident	1,700.00	0.00	1,700.00
To respray rear bumper and tailgate.	1,972.00	0.00	1,972.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	504.00	0.00	504.00
* To remove and install rear windscreen glass to facilitate repairs	545.00	0.00	545.00
* To conduct water leak tests.	71.00	0.00	71.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
(supp)# BLIND RIVET NUT M6	2.70	4.00	0.00	10.80 ✓
BOOTLID	1,298.95	1.00	0.00	1,298.95

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W



Performance Motors

BMW Dealer



Final Report

(supp) # EXPANDING NUT	1.00	2.00	0.00	2.00 ✓
REAR BUMPER TRIM PANEL BOTTOM (BASI	208.45	1.00	0.00	208.45
REAR BUMPER MIDDLE TRIM PANEL (PDC)	266.90	1.00	0.00	266.90
EMBLEM GROMMET	0.95	2.00	0.00	1.90
BMW PLAQUE WITH ADHESIVE FILM	72.85	1.00	0.00	72.85
LETTERING S DRIVE 18I	98.35	1.00	0.00	98.35
LETTERING X1	65.60	1.00	0.00	65.60
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	27.85	1.00	0.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	5,278.00
Total Parts :	2,342.90
Total Labour & Parts :	7,620.90
Deduction for Excess :	
Total Repair Costs less Excess:	7,620.90
GST @7%:	533.46
Grand Total :	8,154.36

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

