



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2302840

INV Date 08/05/2023

Reference CC4/LPC22007452/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 2923M
Insured Veh. YL 2842P
Claim No. 21/22/22/VC05/026101
Policy No. Z21VC05008877
Accident Date 01/08/2022
Inspection Date 04/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22007452/Apa3q2 Date: 08/05/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 2842P	Veh. Inspected	XE 2923M	
Policy No.	Z21VC05008877	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/026101	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	04/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAN TGS	c.c	10518	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WMA06SZZ0HM742613	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/08/2022	Inspection Date	04/08/2022	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2923M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT N/S HEAD LAMP	CRACKED	2,450.60	1,097.00
1	FRONT N/S SIGNAL LAMP	NOT NECESSARY	865.60	-
1	FRONT N/S FOG LAMP	NOT NECESSARY	611.50	-
1	FRONT BUMPER	DISTORTED	3,885.40	3,885.40
1	FRONT BUMPER N/S BRACKET	NOT NECESSARY	540.60	-
1	FRONT BUMPER N/S CORNER GARNISH	DEFORMED	210.00	210.00
1	FRONT N/S STEP ALUMINIUM	CUT	310.00	310.00
1	FRONT N/S STEP BRACKET	NOT NECESSARY	910.40	-
1	FRONT N/S STEP GARNISH MIDDLE	CRACKED	1,856.40	1,856.40
1	FRONT N/S FENDER INNER TRIM (ADDITIONAL)	TORN	750.60	455.00
	LESS 10% DISCOUNT		-1,239.11	-781.38
			11,151.99	7,032.42
	<u>SPECIAL NETT ITEMS</u>			
8	FRONT BUMPER N/S BRACKET SCREW (SN)	NOT NECESSARY	80.00	-
12	FRONT N/S FENDER INNER TRIM CLIPS (SN) (ADDITIONAL)	NECESSARY	120.00	50.00
			200.00	50.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE FRONT DAMAGE PARTS.		900.00	600.00
	TO SPRAY PAINTING.		500.00	300.00
	TO CHECK WIRING.		100.00	30.00
			1,500.00	930.00
	GRAND TOTAL		12,851.99	8,012.42
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,300.00

Report Ref No. CC4/LPC22007452/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 2923M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 2923M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

