

ASS. REC. BY: Taughin

REF: CS/SPF 22007456/Tg, 33

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLV4156A Yr Regn: 2017 / DEC.
Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota CHR C.C. 1797
Colour: Yellow A/C: Insured / Std / NI / NA
Sp. Reading: 116977 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZJK 1020 14148
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / SR / STD A/Rim or _____
Tyre Size: F: 215/60R17
R: 215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Pavanti
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 5/8/22
Survey held at Self
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 482K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Date/Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prell. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Rep. Format : _____
Lump Sum / L.B.L. (\$) _____
Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: _____
Transportation: _____
S + RS. \$ _____
Photos _____
Others _____
TOTAL _____

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SLV 4156A**

Made : Toyota

Model : CHR 1.8 S

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 1,229.54	\$ X 1,229.54
2	Front Bumper Fog Lamp Cover RH	1	\$ 107.42	\$ X 107.42
3	Front Bumper Fog Lamp RH	1	\$ 402.20	\$ X 402.20
4	Front Bumper Sponge	1	\$ 106.83	\$ X 106.83
5	Front Bumper Reinforcement	1	\$ 397.61	\$ X 397.61
6	Front Bumper Side Retainer RH	1	\$ 129.65	\$ X 129.65
7	Front Bumper Side Retainer LH	1	\$ 129.65	\$ X 129.65
8	Front Headlamp Assembly RH	1	\$ 1,871.70	\$ X 1,871.70
9	Front Headlamp Assembly LH	1	\$ 1,871.70	\$ X 1,871.70
10	Front Fender RH	1	\$ 898.40	\$ <i>ht</i> 898.40
11	Front Fender Wheel Arch Garnish RH	1	\$ 180.80	\$ <i>ant</i> 180.80
12	Front Fender Inner Cowling RH	1	\$ 280.30	\$ X 280.30
13	Front Shock Absorber RH	1	\$ 522.70	\$ X 522.70
14	Front Lower Arm RH	1	\$ 805.40	\$ X 805.40
15	Front Knuckle Arm RH	1	\$ 740.50	\$ X 740.50
16	Front Wheel Hub with Bearing RH	1	\$ 697.10	\$ X 697.10
17	Front ABS Sensor	1	\$ 480.20	\$ X 480.20
18	Front Wheel Rim RH	1	\$ 2,303.50	\$ X 2,303.50
19	Front Door RH	1	\$ 1,426.60	\$ <i>bt</i> 1,426.60
20	Front Door Upper Hinge RH	1	\$ 48.90	\$ X 48.90
21	Front Door Lower Hinge RH	1	\$ 48.90	\$ X 48.90
22	Front Door Checker RH	1	\$ 115.70	\$ X 115.70
23	Front Door Lower Garnish RH	1	\$ 366.80	\$ <i>cut</i> 366.80
24	Front Door Step Garnish RH	1	\$ 179.40	\$ X 179.40
25	Front Door Outer Glass Moulding RH	1	\$ 175.40	\$ X 175.40
26	Front Door Inner Weatherstrip RH	1	\$ 325.10	\$ X 325.10
27	Front Door Inner Lock RH	1	\$ 589.10	\$ X 589.10
28	Front Door Inner Trim Board RH	1	\$ 1,097.10	\$ X 1,097.10
29	Front Door Glass Regulator RH	1	\$ 278.50	\$ X 278.50
30	Front Door Glass Regulator Motor RH	1	\$ 779.10	\$ X 779.10
31	Front Door Side Mirror Assembly RH	1	\$ 1,441.90	\$ <i>dis</i> 1,441.90
32	Side Skirt RH	1	\$ 609.70	\$ X 609.70

33	Rear Door RH	1	\$ 1,329.10	\$ 67- 1,329.10
34	Rear Door Upper Hinge RH	1	\$ 48.90	\$ x 48.90
35	Rear Door Lower Hinge RH	1	\$ 48.90	\$ x 48.90
36	Rear Door Checker RH	1	\$ 106.70	\$ x 106.70
37	Rear Door Lower Garnish RH	1	\$ 222.70	\$ cut 222.70
38	Rear Door Step Garnish RH	1	\$ 168.40	\$ x 168.40
39	Rear Door Outer Glass Moulding RH	1	\$ 167.30	\$ x 167.30
40	Rear Door Inner Weatherstrip RH	1	\$ 319.40	\$ x 319.40
41	Rear Door Inner Lock RH	1	\$ 568.70	\$ x 568.70
42	Rear Door Inner Trim Board RH	1	\$ 742.70	\$ x 742.70
43	Rear Door Glass Regulator RH	1	\$ 278.50	\$ x 278.50
44	Rear Door Glass Regulator Motor RH	1	\$ 752.30	\$ x 752.30
45	Rear Fender RH	1	\$ 1,174.40	\$ x 1,174.40
46	Rear Fender Wheel Arch Garnish RH	1	\$ 194.60	\$ x 194.60
47	Rear Fender Inner Cowling RH	1	\$ 159.50	\$ x 159.50
48	Rear ABS Sensor RH	1	\$ 256.40	\$ x 256.40
49	Rear Lower Arm RH	1	\$ 542.30	\$ x 542.30
50	Rear Upper Arm RH	1	\$ 625.40	\$ x 625.40
51	Rear Swing Arm RH	1	\$ 594.70	\$ x 594.70
52	Rear Shock Absorber RH	1	\$ 530.60	\$ x 530.60
53	Rear Linkage RH	1	\$ 101.40	\$ x 101.40
54	Rear Wheel Rim RH	1	\$ 2,303.50	\$ x 2,303.50
55	Rear Taillamp Assembly RH	1	\$ 747.80	\$ x 747.80
56	Rear Tailgate	1	\$ 1,133.90	\$ x 1,133.90
57	Rear Tailgate Weatherstrip	1	\$ 338.20	\$ x 338.20
58	Rear Tailgate Lock	1	\$ 472.40	\$ x 472.40
59	Rear Tailgate Lower Lock	1	\$ 41.40	\$ x 41.40
60	Rear Tailgate Garnish	1	\$ 937.60	\$ x 937.60
61	Rear Tailgate Emblem	1	\$ 62.80	\$ x 62.80
62	Rear Tailgate "C-HR" Emblem	1	\$ 46.00	\$ x 46.00
63	Rear Tailgate "Hybrid Synergy Drive" Emblem	1	\$ 48.40	\$ x 48.40
64	Rear Tailgate Reflector Lamp RH	1	\$ 584.60	\$ x 584.60
65	Rear Tailgate Windscreen Glass Moulding	1	\$ 118.90	\$ x 118.90
66	Rear Bumper	1	\$ 480.20	\$ x 480.20
67	Rear Bumper Lower Guard	1	\$ 378.20	\$ x 378.20
68	Rear Bumper Side Retainer RH	1	\$ 103.40	\$ x 103.40
69	Rear Bumper Side Retainer LH	1	\$ 103.40	\$ x 103.40
70	Rear Bumper Reflector RH	1	\$ 59.80	\$ x 59.80
71	Rear Bumper Reflector Garnish RH	1	\$ 90.80	\$ x 90.80
72	Rear Bumper Reinforcement	1	\$ 369.90	\$ x 369.90
73	Rear Bumper Ultrasonic Sensor	2	\$ 392.80	\$ x 785.60
74	Rear End Panel	1	\$ 722.50	\$ x 722.50
75	Rear End Panel Top Garnish	1	\$ 256.80	\$ x 256.80
Parts Sub Total :				\$ 39,756.40
25% Discount				\$ 9,939.10

PARTS TOTAL : \$ 29,817.30

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Bumper Clips - Set	1	\$ 50.00	\$ X 50.00
2	Front Bumper Fog Lamp Cover RH Clips - Set	1	\$ 30.00	\$ X 30.00
3	Front Fender Inner Cowling Clips RH - Set	1	\$ 50.00	\$ X 50.00
4	Front Fender Wheel Arch Garnish Clips RH - Set	1	\$ 40.00	\$ 100.00 40.00
5	Front Door Inner Trim Board Clips RH - Set	1	\$ 50.00	\$ X 50.00
6	Rear Door Inner Trim Board Clips RH - Set	1	\$ 50.00	\$ X 50.00
7	Rear Fender Inner Cowling Clips RH - Set	1	\$ 50.00	\$ X 50.00
8	Rear Fender Wheel Arch Garnish Clips RH - Set	1	\$ 40.00	\$ 100.00 40.00
9	Rear Bumper Clips - Set	1	\$ 50.00	\$ X 50.00
10	Rear Tailgate Outer Garnish Clips - Set	1	\$ 50.00	\$ X 50.00
11	Rear Tailgate Inner Trim Board Clips - Set	1	\$ 50.00	\$ X 50.00
12	Rear End Panel Top Garnish Clips - Set	1	\$ 40.00	\$ X 40.00
13	Front Fender RH Sealant	1	\$ 150.00	\$ X 150.00
14	Front Door RH Sealant	1	\$ 150.00	\$ X 150.00
15	Rear Door RH Sealant	1	\$ 150.00	\$ X 150.00
16	Rear Fender RH Sealant	1	\$ 150.00	\$ X 150.00
17	Rear Tailgate Sealant	1	\$ 150.00	\$ X 150.00
18	Rear End Panel Sealant	1	\$ 150.00	\$ X 150.00
19	Rear Tailgate Windscreen Glass Sealant	1	\$ 150.00	\$ X 150.00
20	Front Tyre RH	1	\$ 450.00	\$ X 450.00
21	Rear Tyre RH	1	\$ 450.00	\$ X 450.00
SPECIAL NETT TOTAL :				\$ 2,500.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 700 2,000.00
2	To Spray Paint Affected Areas	\$ 700 1,800.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Transfer Front Door Mechanism	\$ 60 150.00
5	To Transfer Rear Door Mechanism	\$ 60 150.00
6	To Transfer Rear Tailgate Mechanism	\$ X 150.00
7	To Remove & Refix Rear Tailgate Windscreen Glass	\$ X 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ X 120.00
9	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ X 250.00
10	To apply anti rust on affected parts	\$ 40 150.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 150.00
12	To Conduct Four Wheel Alignment	\$ X 150.00
13	To Remove & Refix Front Undercarriage	\$ X 450.00
14	To Remove & Refix Rear Undercarriage	\$ X 450.00
15	To Conduct Water Leak Test	\$ X 100.00
16	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 6,800.00

PARTS TOTAL :	\$	29,817.30
SPECIAL NETT TOTAL :	\$	2,500.00
LABOUR TOTAL :	\$	6,800.00
GRAND TOTAL :	\$	39,117.30

Tanjin 97495749
 WP 5/8/22 @ 440 pm
 L/S Resury after repair
 Tanjin @ 11/11/22
 ~6 days

LKK Auto Consultants hence notify
 the **Repairer of the following:**

- To resurvey **before/after** spray painting
- To display **damaged part(s)** during resurvey
- Parts prices are **subject to confirmation**
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Suoplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	383C
Vehicle Details	
Vehicle No.:	SLV4156A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	2ZR8038706
Chassis No.:	ZYX102014148
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,580.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,002.00
COE Rebate Amount:	\$25,358.00
Total Rebate Amount:	\$29,108.00

The information contained herein is correct as at 04 Aug 2022

OK