



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22007457/Kqy3m4 Date: 08/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SG 6346B	Veh. Inspected	SMN 4197L
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/08/22/5012	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	04/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600069133	Colour	METALLIC PEARL WHITE
Odometer	128886 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	WEST LAKE	3 mm
L/H Front Tyre	235/55 R18	WEST LAKE	3 mm
R/H Rear Tyre	235/55 R18	WEST LAKE	4 mm
L/H Rear Tyre	235/55 R18	WEST LAKE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/08/2022	Inspection Date	04/08/2022
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	