

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

CHEW PEI CHI
 C/O 46 LENTOR PLAIN
 SINGAPORE 786548

*NOT Authorized
 11 Day @ 3600hrs
 Resurvey After Paint
 5days*

Date: 5/8/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA HARRIER /SMN4197L		
1 pc	front bumper side retainer	Sm 57.40 X
1 pc	front fender	Bp 975.40 ✓
1 pc	front head lamp	Sm 3,154.00 X
1 pc	front side mirror assy	Bp 974.00 ✓
1 pc	front side mirror cover 179.	Bp 197.50 ✓
1 pc	front door	R 1,456.70 X
1 pc	front door handle	Sm 374.50 X
1 pc	front door handle chrome moulding	Sm 147.60 X
1 pc	front door outer channel moulding 245.60	Sm 293.40 ✓
1 pc	front door frame cover	Sm 215.00 X
1 pc	rear door 1318.10	Bp 1,400.70 ✓
1 pc	rear door outer handle	Sm 374.50 X
1 pc	rear door outer handle chrome moulding	Sm 147.60 X
1 pc	rear door frame cover 105	Sm 215.00 ✓
1 pc	rear fender	R 1,175.00 X
	sub-total	11,158.30
	less 25%	2,789.58
	sub-total	8,368.73
1 pc	front bumper s.nett	R 1,200.00 X
1 pc	rear bumper s.nett	R 1,200.00 X
1 pcs	alloy rim s.nett @ 650	Sm 1,300.00 X
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1,400.00 50d
	To check wiring system.	50.00 2d
	To replace door accessories(2pcs)	120.00 6d
	To apply putty & spray painting on affected areas.	1,450.00 1100d
	To replace alloy rim (2sets)	nn 80.00 X
	Total	15,168.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To supply of damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: