

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22007462/KVY3Q2**Date:** 25/08/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMQ1238G**Insured Vehicle No :** CB197U

Date of Loss: 02/08/2022

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ1238G**

Make &amp; Model: MAZDA 5, 2.0 5 DR WAGON (A)

Engine No: PE10387978

Reg. Date: 09/11/2016 (Man. Year: 2016)

Chassis No: JM6CW1071G0124585

Colour: Metallic Grey

Odometer: 93023 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,645.05	4,701.84	1,943.21	29.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,640.00	1,020.00	38.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,305.05</b>	<b>6,341.84</b>	<b>2,963.21</b>	<b>31.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,305.05</b>	<b>5,050.00</b>	<b>4,255.05</b>	<b>45.73</b>

INSPECTION

Date of Assignment: 04/08/2022

Date Inspected: 05/08/2022

Inspected At:

Caris Autoworks Pte Ltd (HQ)  
160 SIN MING DRIVE, #05-03  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** VERON CHEN**Manager:** KENNETH KONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 24 Aug 2022)	
<b>Parts:</b>	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ1238G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT (REAR)	Bent	1,773.00 FL	*1,637.00 FL
2	1		*BUMPER (REAR)	Buckled	989.00 FL	*962.00 FL
3	1		*BRAKE LAMP INNER (REAR)	Cracked	464.00 FL	*464.00 FL
4	1		*BRAKE LAMP OUTER (REAR)	N/S Serviceable / O/S Cracked	772.00 FL	*386.00 FL
5	1		*WINDSCREEN (REAR)	Shattered	1,326.00 FL	*1,121.00 FL
6	1		*WIPER MOTOR (REAR)	Jammed	347.00 FL	*347.00 FL
7	1		*BOOT LOCK(REAR)	Repair	275.00 FL	*- FL
8	1		*BOOT RUBBER CHANNEL	Serviceable	198.00 FL	*- FL
9	1		*SET REVERSE SENSOR	Shorted	264.60 FS	*200.00 FS
10	1		*MAZDA LOGO	Necessary	68.00 FL	*68.00 FL
11	1		*BODY CLIPS & SCREWS	Necessary	80.00 FS	*80.00 FS
12	1		*END PANEL (REAR)	Bent	595.30 FL	*542.30 FL
13	2		*BRAKE REFLECTOR	Serviceable	193.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,345.10</b>	<b>5,807.30</b>
<b>- List Item Discount on L Items 10.00/20.00% (\$)</b>	700.05	1,105.46
<b>Total Parts (\$)</b>	<b>6,645.05</b>	<b>4,701.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL KNOCKING	New	1,200.00	700.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	WIRE CHECKING & DIAGNOSTIC	New	100.00	20.00
4	LABOUR CHARGE FOR REMOVE & INSTALL WINDSCREEN	New	280.00	120.00
5	WHEEL ALIGNMENT	New	80.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >