

CARIS AUTOWORKS PTE LTD
 160 SIN MING DRIVE
 #05-03 SIN MING AUTOCITY
 SINGAPORE 575722
 (COMPANY REGISTRATION NO: 200923135D)
 TEL: 62589831
 FAX: 62585349

*Not Authorized
 1/10/04 @ 50504
 Recovery After Paint
 6 days*

ESTIMATE REPAIR COST FOR MAZDA (5) REG NO : SMQ 1238 G

SS

1 PC	BOOT (REAR)	1637.00			
1 PC	BUMPER (REAR)	962			
2 PCS	BRAKE LAMP INNER (REAR)				
2 PCS	BRAKE LAMP OUTER (REAR)				
1 PC	WINDSCREEN (REAR)	1121.00	<i>All Part</i>		
1 PC	WIPER MOTOR (REAR)				
1 PC	BOOT LOCK (REAR)				
1 PC	BOOT RUBBER CHANNEL				
1 SET	REVERSE SENSOR				
1 PC	MAZDA LOGO				

<i>Aj</i>	1773.00	<i>✓</i>
<i>An</i>	989.00	<i>✓</i>
<i>CU</i>	464.00	<i>✓</i>
<i>olsem</i>	772.00	<i>✓ 386</i>
<i>plotton</i>	1326.00	<i>✓</i>
<i>Im</i>	347.00	<i>✓</i>
<i>A</i>	275.00	<i>✓</i>
<i>In</i>	198.00	<i>✓</i>
<i>stom</i>	294.00	<i>✓ 200in</i>
<i>nu</i>	68.00	<i>✓</i>

TOTAL	<i>209</i>	6506.00
LESS 10%		650.60
TOTAL		5855.40

LABOUR & MISC CHARGES

- PANEL KNOCKING
- SPRAY PAINTING
- BODY CLIPS & SCREWS
- WIRE CHECKING & DIAGNOSTIC
- LABOUR CHARGE FOR REMOVE & INSTALL WINDSCREEN
- WHEEL ALIGNMENT

<i>Fod</i>	1200.00	
<i>nu</i>	1000.00	<i>Bood</i>
<i>nu</i>	80.00	
<i>nu</i>	100.00	<i>2ok</i>
<i>nu</i>	280.00	<i>12ok</i>
<i>nu</i>	80.00	<i>X</i>

9383.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CARIS AUTOWORKS PTE LTD
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722
(COMPANY REGISTRATION NO: 200923135D)
TEL: 62589831
FAX: 62585349

ESTIMATE REPAIR COST FOR MAZDA (S) REG NO : SMQ 1238 G

SUPPLEMENTARY PARTS

			\$
1 PC	END PANNEL (REAR)	542.70	A 595.30 ✓
2 PCS	BRAKE REFLECTOR (PER PC \$96.60)		B 193.20P X