

ASS. REC. BY: Tauhin

REF:

CS/CT122007465/T9y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £146k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SMG 1195Z Yr Regn: 2020 Feb.Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz A200 AMG 1332Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 51786

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1770872 V015553Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R18R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 0 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 5/8/22Survey held at BifrostDes. of Damages ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Check tyres & brake of vehicle, drove the car to check brake, brake is
in order and tyres in good condition.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / I.B.R. (\$ _____)

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMG1195Z

Make & Model: Mercedes Benz A200

Chassis number: WDD1770872V015553

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ <i>bt</i> 1,776.30
2	Bonnet RH hinge	1	\$? 95.50
3	Bonnet LH hinge	1	\$? 95.50
4	Bonnet lock	1	\$? 178.20
5	Bonnet lock catch	1	\$? 55.60
6	Front bumper (AMG)	1	\$ <i>ang</i> 1,467.80
7	Front bumper upper rubber seal	1	\$ 114.60
8	Front bumper centre emblem	1	\$ <i>ang</i> 71.06
9	Front bumper LH side grille	1	\$? 78.40
10	Front bumper LH side grille garnish	1	\$? 139.00
11	Front bumper RH side grille	1	\$ <i>x</i> 78.40
12	Front bumper RH side grille garnish	1	\$ <i>x</i> 139.00
13	Front bumper sensor rubber seal	6	\$? 78.30
14	Front bumper sensor holders	4	\$? 104.00
15	Front bumper sensor wire harness	1	\$ <i>x</i> 187.57
16	Front bumper LH side sensor	1	\$? 178.65
17	Front bumper RH side sensor	1	\$? 178.65
18	Front bumper lower centre grille	1	\$? 253.00
19	Front bumper number plate garnish	1	\$ <i>dl</i> 123.40
20	Front bumper towing cover	1	\$ <i>aut</i> 78.20
21	Front bumper centre inner upper bracket	1	\$? 211.10
22	Front bumper centre inner lower bracket	1	\$? 201.00
23	Front bumper lower trim strip	1	\$? 333.03
24	Front bumper inner sponge	1	\$? 153.40
25	Front bumper reinforcement	1	\$? 575.30
26	Front bumper reinforcement RH bracket	1	\$? 178.30
27	Front bumper reinforcement LH bracket	1	\$? 178.30
28	Front bumper lower centre spoiler	1	\$ <i>dis</i> 389.00
29	Front bumper lower centre spoiler chrome moulding	1	\$ <i>x</i> 92.10
30	Front bumper RH inner air duct	1	\$? 68.40
31	Front bumper LH inner air duct	1	\$? 68.40
32	Front bumper RH side bracket holder	1	\$? 118.00
33	Front bumper LH side bracket holder	1	\$? 118.00
34	Front grille	1	\$ <i>ang</i> 773.20
35	Front grille emblem	1	\$ <i>aut</i> 178.00
36	Front grille emblem bracket	1	\$ <i>dis</i> 102.20
37	Front grille RH chrome moulding	1	\$ <i>aut</i> 83.30
38	Front grille LH chrome moulding	1	\$ <i>aut</i> 83.30
39	Front grille inner air guide	1	\$? 203.10

40	Front grille outer cover	1	\$ 178.00
41	Front grille RH sensor	1	\$? 178.65
42	Front grille LH sensor	1	\$? 178.65
43	Front grille sensor holders	2	\$? 30.00
44	Front grille radar sensor	1	\$? 1,546.50
45	Front grille radar sensor bracket	1	\$? 67.80
46	RH headlamp assy	1	\$? 3,121.90
47	RH headlamp control unit	1	\$? 595.05
48	LH headlamp assy		\$ Cua 3,121.90
49	LH headlamp control unit	1	\$? 595.05
50	Front RH fender	1	\$ Ry 612.57
51	Front RH fender splash shield	1	\$ X 178.96
52	Front LH fender	1	\$ ht 612.57
53	Front LH fender splash shield	1	\$ X 178.96
54	Front air cleaner box air duct	1	\$? 304.20
55	Support centre panel	1	\$? 178.20
56	Support panel	1	\$? 700.60
57	Support brace panel	1	\$? 98.00
58	Aircon condenser	1	\$? 1,178.06
59	Aircon suction pipe	1	\$? 315.60
60	Aircon discharge pipe	1	\$? 367.40
61	Aircon aluminium pipe	1	\$? 324.70
62	Radiator	1	\$? 1,390.80
63	Radiator air vent	1	\$? 353.20
64	Radiator air guide	1	\$? 176.00
65	Radiator fan assy	1	\$? 961.30
66	Turbo intercooler	1	\$? 1,456.66
67	Turbo intercooler inlet hose	1	\$? 245.60
68	Turbo intercooler outlet hose	1	\$? 267.04

\$ 29,092.48

Parts less 10% \$ 2,909.25

Total \$ 26,183.23

No.	Special Nett Items		Amount S\$
1	Bonnet art work sticker	1	\$? 850.00
2	Bonnet insulator clips	1set	\$ 300 100.00
3	Front bumper clips	1set	\$ 300 100.00
4	Front bumper rivets	1set	\$ 300 70.00
5	Front bumper art work sticker	1	\$? 550.00
6	Front bumper lower spoiler	1	\$ dis 1,850.00
7	Front number plate	1	\$ cut 100.00
8	Front number plate holder	1	\$ huv 70.00
9	Front grille clips	1set	\$ 30 90.00
10	Front RH fender art work sticker	1	\$ X 550.00
11	Front RH fender splash shield clips	1set	\$ X 70.00
12	Front LH fender art work sticker	1	\$ X 550.00
13	Front LH fender splash shield clips	1set	\$ X 70.00
14	Radiator coolant	1	\$? 180.00

} 45
neg

