

VEHICLE NO : **SMV3621T**
 MODEL : **TOYOTA VIOS**
 DATE/TIME ACCIDENT : 30.07.2022/1745
 DATE OF REG : 28.09.2020
 CHASSIS : MR2B23F3601211308

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00 <i>60</i>
2	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 ✓
3	FRONT BUMPER TOP COVER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
4	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 x.
5	FRONT UPPER GRILLE CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
6	FRONT CENTER GRILLE CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 x
7	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
8	FRONT FENDER INNER COWLING CLIP (SET) <i>Neu</i>	2	\$ 30.00	\$ 60.00 x.

140 TOTAL \$ 320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	1,200.00 <i>500</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	1,200.00 <i>600</i>
3	REFOCUS HEADLAMP BEAM	\$ 120.00	120.00 <i>30</i>
4	REMOVE CONDENSER /TOP UP GAS	\$ 80.00	80.00 <i>60</i>
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	180.00 <i>x</i>

1190

*Adrian King
 1/s 02/08/22*

TOTAL \$ 2,780.00

TOTAL PARTS COST ~~\$ 10,354.49~~
 TOTAL LABOUR COST ~~\$ 2,780.00~~
 TOTAL REPAIR COST ~~\$ 13,134.49~~

LKK:AS *10,354.49*
 To resurvey before repair painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

05 Days

total: 5412.36

L/S: 4.31k

4.31k