

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007469/AGA3Q2**Date:** 14/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700066323
Claimant Vehicle No :	SMZ1798J	Insured Vehicle No :	SJE8391Z
Date of Loss:	01/08/2022	Nature of Claim:	TP
		Claim No:	9228803127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ1798J		
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Engine No:	HIDDEN
Reg. Date:	15/11/2021 (Man. Year: 2021)	Chassis No:	LRW3F7FA0MC384416
Colour:	Red	Odometer:	0 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,837.00	7,193.30	7,643.70	51.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	2,290.00	900.00	28.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,027.00	9,483.30	8,543.70	47.39
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	18,027.00	7,500.00	10,527.00	58.40
+ GST 8.00/8.00% (S\$)	1,442.16	600.00	842.16	58.40
Nett Amount (S\$)	19,469.16	8,100.00	11,369.16	58.40
+ Car Rental (9.0 x S\$130.00/day) (S\$)		1,170.00		
Nett Liability (S\$)		9,270.00		
Global Sum Settlement (S\$)		9,200.00		

INSPECTION

Date of Assignment:	02/08/2022		
Date Inspected:	02/08/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	2,300.00 FL	*893.00 FL
2	1		*FRT BUMPER LH RETAINER	Not Necessary	140.00 FL	*- FL
3	1		*FRT BUMPER LOWER GARNISH	Cut	320.00 FL	*320.00 FL
4	1		*FRT LH RIM	Cut	1,670.00 FL	*1,078.00 FL
5	1		*RH TAILLAMP	Cracked	880.00 FL	*380.00 FL
6	1		*REAR BUMPER	Deformed	2,300.00 FL	*783.00 FL
7	1		*REAR BUMPER RH RETAINER	Necessary	180.00 FL	*180.00 FL
8	1		*REAR BUMPER REVERSE SENSOR (3 PCS)	Damaged (2 PCS ONLY)	840.00 FL	*560.00 FL
9	1		*REAR RH FENDER	Buckled	2,860.00 FL	*1,565.00 FL
10	1		*RH BODY LIGHT	Cut	380.00 FL	*380.00 FL
11	1		*REAR BUMPER RH REFLECTOR	Cut	180.00 FL	*180.00 FL
12	1		*REAR BUMPER LOWER LIP	Cut	480.00 FL	*480.00 FL
13	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
14	1		*REAR BUMPER SPONGE	Not Necessary	260.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,010.00 FL	*- FL
16	1		*REAR RH RIM	Cut	1,680.00 FL	*1,078.00 FL
17	1		*REAR RH TAILGATE REFLECTOR	Not Necessary	780.00 FL	*- FL
18	1		*REAR RH FENDER AIR GUARD	Not Necessary	110.00 FL	*- FL
19	1		*REAR RH QUARTER GLASS GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,480.00	7,987.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,643.00	793.70
Total Parts (\$)	14,837.00	7,193.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	1,000.00
2	SPRAY PAINTING	New	1,500.00	1,100.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	80.00
5	ALIGNMENT	New	80.00	80.00
			Gross Labour Cost (S\$)	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >