

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMJ7590K

Make & Model: Hyundai Avante

Chassis number: KMHD841CMKU879134

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$	
1	Bootlid 1782	1	\$ 1782 1,782.40	
2	Bootlid centre emblem	1	\$ 34.90 34.90	
3	Bootlid "Avante" emblem	1	\$ 45.90 45.90	
4	Bootlid reverse camera	1	\$ X 826.10	nn
5	Bootlid lock	1	\$ X 125.30	nn
6	Bootlid RH hinge	1	\$ X 94.30	nn
7	Bootlid LH hinge	1	\$ X 94.30	nn
8	Bootlid weatherstrip	1	\$ X 109.10	nn
9	Bootlid RH lamp	1	\$ X 664.10	nn
10	Bootlid LH lamp	1	\$ X 664.10	nn
11	Rear bumper 498.80	1	\$ 498.80 459.80	
12	Rear bumper lower garnish 340.60	1	\$ 340.60 353.20	340.60
13	Rear bumper number plate garnish	1	\$ 29.90 29.90	
14	Rear bumper LH number plate lamp	1	\$ 28.30 28.30	
15	Rear bumper RH number plate lamp	1	\$ 28.30 28.30	
16	Rear bumper RH side lamp	1	\$ X 201.50	nn
17	Rear bumper LH side lamp	1	\$ X 201.50	nn
18	Rear bumper RH side retainer	1	\$ X 33.10	nn
19	Rear bumper LH side retainer	1	\$ 33.10 33.10	
20	Rear bumper reinforcement 294.80	1	\$ 294.80 302.10	294.80
21	Rear bumper reinforcement RH bracket	1	\$ X 78.60	nn
22	Rear bumper reinforcement LH bracket	1	\$ X 78.60	nn
23	Rear bumper reinforcement RH upper bracket	1	\$ X 12.00	nn
24	Rear bumper reinforcement LH upper bracket	1	\$ X 12.00	nn
25	Rear bumper reinforcement RH lower bracket	1	\$ 12.00 12.00	
26	Rear bumper reinforcement LH lower bracket	1	\$ 12.00 12.00	
27	RH taillamp	1	\$ X 1,052.10	nn
28	LH taillamp 1052.10	1	\$ 1052.10 1,052.10	
29	End panel	1	\$ 478.00 478.00	
30	End panel inner garnish	1	\$ 59.80 59.80	
31	Rear antenna sensor	1	\$ X 55.00	nn
32	Rear RH fender inner trim	1	\$ X 209.00	nn
33	Rear LH fender inner trim	1	\$ 209.00 209.00	
34	Spare tyre panel top cpver	1	\$ X 640.80	nn
35	Exhaust silencer	1	\$ X 793.20	nn
36	Exhaust silencer gasket	1	\$ X 32.00	nn

\$ 10,897.50
 Parts less 20% \$ 2,179.50
 Total \$ 8,718.00

No.	Special Nett Items	Qty	Amount S\$	
1	Bootlid inner trim clips	1set	\$ X 80.00	nn
2	Bootlid sealant	1	\$ X 100.00	nn
3	Rear bumper clips	1set	\$ 300 100.00	nn
4	Rear bumper lower garnish clips	1set	\$ X 60.00	nn
5	End panel inner garnish clips	1set	\$ X 45.00	nn
6	End panel joint sealant	1	\$ X 100.00	nn
7	Rear RH fender inner trim clips	1set	\$ X 80.00	nn
8	Rear LH fender inner trim clips	1set	\$ 200 80.00	nn
9	Rear number plate	1	\$ X 70.00	nn
10	Rear number plate frame	1	\$ X 50.00	nn
Total:			\$ 765.00	

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 700 1,400.00
2	Spray painting on affected areas and panels	\$ 700 1,200.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 100.00
5	Remove and replace rear bumper reverse sensors to carry repair	\$ 30 100.00
6	Remove and replace rear inner trims, garnish and boards to carry repair	\$ 60 320.00
7	Remove and replace exhaust silencer and gasket to carry repair	\$ X 180.00
8	Remove and replace bootlid reverse camera to carry repair	\$ X 150.00
Total:		\$ 3,530.00

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Taufhin 974957M
 5/8/22 @ 5pm
 L/S Resurvey after repair
 taufhin@lkkauto.hk
 today

Spare Parts: \$ 8,718.00
 Special Nett: \$ 765.00
 Labour: \$ 3,530.00

LKK Auto Consultants hence notify the Repairer of the following: **13,013.00**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: