

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

02-10-22

Marcus.

Date Of Accident : 04-08-2022

OUR REF : SLK 272G/T/22

date in/out: 04/08/22 to 30/08/22

Gilbert Goh Soo Heng

Blk 16 Jalan Tenteram

#12-112

Singapore 321016

*NOT Authorized
all*

5/8/22

*1/5 \$ 28,000 /
20 days*

ESTIMATE BILL ON VEH. NO. : SLK 272G

MODEL : HONDA CIVIC

CHASSIS NO.: MRHFC5650GT000749

LIST ITEM

Front Bumper		DIS	579.20	—
Front Bumper Side Retainer	2pcs @ 16.50	one	33.00	—
Front Bumper Air Grille		Torn	50.20	—
Front Bumper Lower Center Garnish		DIS	76.20	—
Front Bumper Clips	18pcs @ 3.50	all	63.00	—
Front Bumper Reinforcement		DIS	377.90	—
Front Bumper Top Rubber Beading		Torn	26.80	—
Front Bumper Top Rubber Beading Clips	12pcs @ 3.50	all	42.00	X
Front Bumper Top Panel		Scr	138.60	—
Fog Lamp Cover	2pcs @ 28.60	MSW	57.20	1pc
Fog Lamp Cover Center Garnish	2pcs @ 60.80	all	121.60	X
Fog Lamp Cover Chrome	2pcs @ 64.20	all	128.40	X
Head Lamp (LED)	2pcs @ 1387.20	one	2,774.40	—
Head Lamp Lower Bracket	2pcs @ 38.40	one	76.80	—
Head Lamp Garnish	2pcs @ 95.80	miss o/s one	191.60	—
Front Grille Garnish		DIS	120.80	—
Front Grille Clips	8pcs @ 3.50.	all	28.00	X

Front Support Panel		Bent/Tru	574.20	/
Bonnet Hinge	2pcs @ 42.80	Tru	85.60	/
Bonnet Lock		Bent	85.40	/
Bonnet Lock Cable (Frony & Rear)	2pcs @ 49.20	Tru	98.40	/
Bonnet Stand		rr	43.70	X
Bonnet Stand Clips	2pcs @ 6.80	rr	13.60	X
Front Support Top Cover		Dis	27.70	/
Front Support Top Cover Clips	6pcs @ 3.50	rr	21.00	/
Front Fender RH & LH	2pcs @ 480.80	Dis/Suc	961.60	/
Front Fender Inner Bracket	2pcs @ 32.50	rr	65.00	X
Front Fender Splash Shield	2pcs @ 89.40	Tru	178.80	/
Front Fender Splash Shield Clips	18pcs @ 3.50	rr	63.00	/
Front Fender Stay (Upper) RH		Bent	24.70	/
Front Fender Stay (Bottom) RH		Bent	14.80	/
Front Fender Enclosure Panel		Bent	29.80	/
Front Bumper Under Cover (Center)		Dis	233.80	/
Front Bumper Under Cover Clips		rr	21.00	/
Engine Under Cover		Dis	232.40	/
Engine Under Cover Clips	10pcs @ 3.50	rr	35.00	X
Front Wheel Housing Panel RH		rr	694.20	X
Front Wheel Housing Extension Panel (Front)		Bent	155.20	/
Front Wheel Housing Extension Panel (Rear)		Bent	212.40	/
Front Wheel Housing Panel Fender Bracket		Bent	61.70	/
Front Chassis Sub Frame RH		rr	191.80	X
Air Cond Condensor		Bent/Tru	704.20	/
Air Cond Condensor Top Mounting	2pcs @ 39.40	Tru	78.80	/
Air Cond Condensor Bottom Mounting	2pcs @ 38.70	rr	77.40	X

Air Cond Condensor Side Air Grille Garnish	2pcs @ 80.40	Torn	160.80	/
Air Cond Suction Pipe		Surf	158.20	/
Air Cond Liquid Pipe		nn	96.80	X
Air Cond Discharge Pipe		nn	139.40	X
Air Cond Fan Motor <i>cowling</i>		one	681.40	/
Air Cond Fan Blade		nn	72.40	X
Front Fender Top Sponge RH		Torn	68.10	/
Front Fender Bracket (Front & Rear Bottom)	2pcs @ 49.60	Replaced	99.20	X
Front Fender Top Garnish Cover RH & LH	2pcs @ 51.60	Dis	103.20	/
Front Fender Top Garnish Cover Clips	8pcs @ 3.50	acc	28.00	/
Front Fender Inner Sponge		NS	61.80	X
Wiper Garnish		Dis	149.20	/
Wiper Garnish Clipss	6pcs @ 3.50	nn	21.00	X
Wiper Garnish Side Rubber	2pcs @ 39.40	o/s torn	78.80	IPC
Wiper Arm	2pcs @ 89.40	o/s DD	178.80	IPC
Engine Mounting RH		Torn	162.40	/
Gear Box Mounting		nn	189.70	X
Engine Under Mounting		Torn	149.20	/
Radiator		Surf here	1,100.40	/
Radiator Top Mounting	2pcs @ 42.70	nn	85.40	X
Radiator Bottom Mounting	2pcs @ 38.80	nn	77.60	X
Radiator Top Hose		nn	20.40	X
Radiator Bottom Hose		nn	21.70	X
Radiator Fan Motor		nn	696.20	X
Radiator Fan Cowing		nn	149.10	X
Radiator Fan Blade		nn	72.40	X
Exhaust Soft Pipe		DD	742.70	/
Exhaust Oxygen Sensor		Dye	594.20	/

Wiper Washer Tank		Dis	84.20	/
Wiper Washer Tank Motor		Dye	59.70	/
Wiper Washer Tank Neck		De	24.50	/
Wiper Washer Tank Cap		Mos	11.40	/
Front Door RH		Dis	924.70	/
Front Door Hinge (Top & Bottom)	2pcs @ 39.70	Bent	79.40	/
Front Door Weatherstripe		ALL	149.20	/
Front Door Lower Rubber Beading		ALL	24.30	/
Front Door Checker		11	42.70	X
Front Door Window Frame Top Moulding		Bent	59.40	/
Front Door Window Regulator With Motor		Bent/Jm	289.40	/
Front Door Window Glass		SRO	349.20	/
Front Door Window Glass Channel Bracket		11	49.20	X
Front Door Window Glass Channel Rubber		7MI	79.20	/
Front Door Window Glass Outer Moulding		Bent	58.70	/
Front Door Window Frame Black Sticker		ALL	24.30	/
Front Door Window Frame Center Garnish		11	30.40	X
Front Door Outer Handle		CU7	189.40	/
Front Door Outer Handle Knob		CU7	60.80	/
Front Door Inner Handle		CRa	94.20	/
Front Door Inner Trim Board	398.40	De/10/11	398.40	/
Front Door Inner Trim Board Clips	10pcs @ 3.50	ALL	35.00	/
Front Door Window Switch		11	280.80	X
Front Door Stopper		11	8.90	X
Front Door Outer Pillar		DS	984.30	/
Front Door Inner Pillar		11	842.70	X
Front Door Inner Lock		Dege	192.40	/

16800.3

Rear Door RH		Body	825.40	/
Rear Door Hinge (Top & Bottom)	2pcs @ 39.40	Surf	78.80	/
Rear Door Checker		in	42.70	X
Rear Door Weatherstripe		neu	139.80	/
Rear Door Stopper		in	8.90	X
Rear Door Window Regulator With Motor		Surf	259.40	/
Rear Door Window Glass Channer Bracket		in	49.20	X
Rear Door Window Glass Channer Rubber		in	79.30	X
Rear Door Window Glass Outer Moulding		Tru	69.80	/
Rear Door Window Frame Black Sticker		neu	84.20	/
Rear Door Window Frame Center Garnish		in	34.70	X
Rear Door Inner Trim Board		del/Tru	387.40	/
Rear Door Inner Trim Board Clips	10pcs @ 3.50	neu	35.00	/
Rear Door Center Pillar (Outer)		R	781.60	X
Dashboard Fascia		Torn	796.20	/
Steering Air Bag		Activated	1,827.40	/
Steering Air Bag Clock Spring		Activated	394.20	/
Passenger Air Bag		Activated	1,868.90	/
Air Bag Control Module		Activated	918.80	/
Front Seat Belt RH & LH	2pcs @ 729.40	Activated	1,458.80	/
Air Bag Chassis Crash Sensor RH & LH	2pcs @ 122.90	Activated	245.80	/
Wiper Nozzle	2pcs @ 39.40	in	78.80	X
Speedo meter Garnish With Air Cond Vent		Cur	167.40	/
Front Cross Member		Surf/Tru	1,285.40	/
Front Knuckle Arm RH		Surf	241.20	/
Front Lower Arm RH		Surf	289.40	/
Front Wheel Bearing Kit RH		neu	89.20	/
Front Wheel Bearing Hup RH		Surf	194.20	/

Steering Rack Assy		11	2,298.70	X
Drive Shaft Assy RH		1m	927.40	✓
Front Anti Roll Bar		Smf	189.40	✓
Front Anti Roll Bar Linkage		Smf	88.40	✓
Air Cleaner Box Assy		Smf	88.70	✓
Air Cleaner Box Air Duct		Cm	61.60	✓
Air Cleaner Resonator		Smf	71.20	✓
Air Cleaner Inlet Hose		11	39.70	X
Auto Gear Box Assy		n	8,845.60	X
Auto Gear Box Oil Cooler		Smf	298.40	✓
Auto Gear Box Oil Cooler Hose		1m	138.90	✓
Front Windscreen Glass		Smf	1,814.20	✓
Front Windscreen Glass Mounting		1m	149.80	✓
Front Windscreen Glass Clips	14pcs @ 4.50	11	63.00	X
Front Windscreen Glass Inner Seal		1m	50.00	✓
			<hr/> 49,313.10	
	Less Discount 20%:		<hr/> 9,862.62	
			<hr/> 39,450.48	

SPECIAL NETT ITEM

Front Bumper Lower Spoiler (Acc)		11	600.00	X
Fog Lamp	2pcs @ 400.00	11	800.00	X
Fog Lamp Bulb (LED) Acc	2pcs @ 80.00	11	160.00	X
Front Grille (Acc)		Cm	450.00	200
Front Grille Badge (Acc)		1m	60.00	20
Bonnet (Carbon Fibre)		Dis	1,200.00	400
Front Door Window Glass Solar Film		1m	140.00	60
Steering Wheel (Carbon Fibre)		work	1,600.00	800
Front Absorber (Acc) RH		Page	600.00	✓

Sport Rim Assy (RH & LH Front)

2pcs @ 900.00 woped 600x22 1,800.00 1200

Tyre Assy RH Front

LP 200x702 cur 350.00 140

Auto Transmission Fluid

11 160.00 X

Front Windscreen Glass Sealant

1pc 60.00 40

Front Windscreen Glass Solar Film (Acc)

1pc 180.00 150

ERP Bracket

1pc 25.00 20

Front Number Plate

Daye 45.00 40

Front Number Plate Casing (Carbon Fibre)

11 60.00 X

Front Window Frame Moulding Black Sticker RH

Aspeth 30.00 X

Rear Window Frame Moulding Black Sticker RH

" 30.00 X

Front Window Center Garnish Black Sticker RH

" 30.00 X

Rear Window Center Garnish Black Sticker RH

" 30.00 X

Front Door Outer Handle Black Sticker

" 50.00 X

Front Door Window Frame Top Moulding Sticker

" 30.00 X

Rear Door Window Frame Top Moulding Sticker

" 30.00 X

Front Fender Lamp RH (Acc)

one 60.00 25

LABOUR CHARGE

Towing

120.00 80

To Check & Reconnect Snap Wiring

280.00 30

To Tuff Coat Affected Areas

200.00 120

To Remove & Refix Engine & Gear Box Assy

800.00 380

To Remove & Refix Front Under Carriage Components

580.00 350

To Remove & Refix Dashboard

380.00 280

To Remove & Refix Front Windscreen

180.00 120

To Remove & Refix Radiator & Top Top Up Coolant

180.00

To Remove & Refix Air Cond Condensor & Top Up Gas

180.00 } 100

To Remove & Refix Front Sport Rim & Contact Wheel Blancing

200.00 30

To Remove & Refix Air Bag System, Seat Belt & Reset Air Bag Control Module

450.00 300

To Respray Affected Areas	2,200.00	1600
To Renew Damaged Parts, Straighten & Repair Aligned All Parts	3,200.00	2000
To adjust Chassis Alignment On Car O-Liner	380.00	X
To Adjust Computer 4 Wheel Alignment	180.00	60
To Remove & Refix Interior Upholstery, Car Seats	300.00	60
	<hr/>	
	57,840.48	
	GST 7%:	523.88
TOTAL AMOUNT :	<hr/>	<hr/>
	58,364.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 32335
202

25868
3695