

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIS22007481/UVY3E2

**Date:** 23/08/2022

### REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SDK9600D

**Insured Vehicle No :** SLE4060G

Date of Loss: 31/07/2022

Nature of Claim: TP Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK9600D**

Make & Model: MERCEDES-BENZ S600L, 5.5 (A)

Engine No: 17698030010063

Reg. Date: 13/04/2018 (Man. Year: 2017)

Chassis No: WDD2221832A370349

Colour: Black

Odometer: 97685 km

Engine Capacity: 3982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40Z R20

Rear Tyre Size: 275/35Z R20

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,400.55	0.00	14,400.55	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	1,800.00	2,470.00	57.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>18,670.55</b>	<b>1,800.00</b>	<b>16,870.55</b>	<b>90.36</b>

### INSPECTION

Date of Assignment: 05/08/2022

Date Inspected: 15/08/2022 Inspected At:

Tick Hai Motor & Welding Services - Kaki Bukit (HQ)  
BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2022)
<b>Parts:</b>	143	MERCEDES-BENZ S600L 5.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDK9600D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (LH)	Repair	4,001.40 FL	*- FL
2	1		*SET REAR DOOR TRIMBOARD CLIP	Not Necessary	35.10 FL	*- FL
3	1		*REAR DOOR WEATHERSTRIP (LH)	Not Necessary	345.15 FL	*- FL
4	1		*REAR FENDER (LH)	Repair	5,382.00 FL	*- FL
5	1		*SET REAR FENDER INNER GARNISH CLIP	Not Necessary	17.55 FL	*- FL
6	1		*SET REAR WINDSCREEN MOULDING	Not Necessary	163.80 FL	*- FL
7	1		*REAR BOOT	Repair	3,036.15 FL	*- FL
8	1		*SET REAR BOOT TRIMBOARD CLIP	Not Necessary	29.25 FL	*- FL
9	1		*S560 EMBLEM	Not Necessary	80.27 FL	*- FL
10	1		*CC EMBLEM	Not Necessary	119.34 FL	*- FL
11	1		*MERCEDES CENTRE LOGO	Not Necessary	64.35 FL	*- FL
12	1		*9 G-TRONIC EMBLEM	Not Necessary	84.86 FL	*- FL
13	1		*TAILLAMP (LH)	Not Necessary	1,308.06 FL	*- FL
14	1		*REAR TYRE RIM (LH)	Repair	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,867.28</b>	<b>0.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,466.73	0.00
<b>Total Parts (\$\$)</b>	<b>14,400.55</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING	New	100.00	0.00
2	TO TRANSFER LHR DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR	New	120.00	0.00
3	TO TRANSFER REAR BOOT COMPONENT FROM OLD BOOT TO NEW BOOT	New	200.00	0.00
4	TO REMOVE & INSTALL REAR INTERIOR GARNISHES ETC TO FACILITATE REPAIR	New	220.00	0.00
5	TO REMOVE & INSTALL REAR WINDSCREEN	New	150.00	0.00
6	TO REMOVE & INSTALL LHR TYRE RIM	New	80.00	0.00
7	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING	New	1,600.00	800.00
8	TO PUTTY AND RESPRAY AFFECTED AREAS	New	1,800.00	1,000.00
<b>Gross Labour Cost (\$)</b>			<b>4,270.00</b>	<b>1,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >