

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Billy Tan

Date: 28 Nov 2022

Preliminary Advice

Insured Vehicle No	: GBE9499K	Accident Date	: 03/08/2022
TP Vehicle No	: PC6527C	Assignment Date	: 05/08/2022
Make	: TOYOTA HIACE	Est. Duration of Repair	: 6
Date of Inspection	: 11/08/2022		
Inspection At	: SC AUTO INDUSTRIES (S) PTE LTD (HQ) 51 SENOKO ROAD, #03-01 SINGAPORE 758133		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,087.20
Revised Amount	:S\$	9,997.03
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,997.03

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.