

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0663/2022/GW
DATE : 5-Aug-22
WIP : 22382

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

14 days - ok - Johnny Boo

11-Dec-22

OWNER'S NAME : PREMIUM LEASING PTE LTD
ADDRESS : 9 LENG KEE RD
SINGAPORE 159090
TELEPHONE : HP +65 85189509
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMD 8625 U**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 7/9/2018
ENGINE NO : CHZ936774
CHASSIS NO : WAUZZZZ8VXJ1065657
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-22
PLACE OF ACCIDENT : CAR PARK AT OCEAN WAY

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 8625 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID.	S/N \$	280.00	\$	280.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	\$	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00		
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	\$	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	\$	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$	1,400.00
SUB-TOTAL LABOUR CHARGES		:	\$ 4,280.00	\$	3,830.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 8625 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		<i>\$ 3,830.00</i>
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	<i>\$ 700.00</i>
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORAGNISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,300.00	<i>\$ 4,000.00</i>
9	TO RESPRAY REAR BUMPER, LHS REAR DOOR, DOOR HANDLE, LHS FRONT DOOR, LHS REAR FENDER, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$	7,000.00	<i>\$ 4,325.00</i>
10	TO RENEW LHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	<i>\$ 192.00</i>
TOTAL LABOUR CHARGES		:	\$ 18,752.00	<i>\$ 13,047.00</i>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 8625 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,317.00		
2	REAR WHEEL HOUSING LINER ADAPTER - LH	1	\$ 42.00		
3	REAR BUMPER GUIDE SECTION - LH	1	\$ 75.00		
4	REAR FENDER - LH	1	\$ 4,445.00	\$	3,556.00
5	REAR WINDSCREEN	1	\$ 905.00	\$	724.00
6	REAR SIDE WINDOW - LH	1	\$ 635.00	\$	508.00
7	PRIMER	2	\$ 44.00	\$	34.72
8	REAR WHEEL HOUSING LINER -LH	1	\$ 260.00		
9	FRONT DOOR - LH	1	\$ 3,265.00	\$	2,612.00
10	FRONT DOOR OUTER SEAL - LH	1	\$ 179.00	\$	142.80
11	BONDING AGENT	1	\$ 51.00	\$	40.56
12	CLEANING SOLUTION	1	\$ 74.00	\$	58.96
13	APPLICATOR	1	\$ 9.00		
14	FRONT DOOR ATTACHMENT PARTS - LH	1	\$ 134.00		
15	FRONT DOOR CATCH - LH	1	\$ 105.00		
16	FRONT DOOR MOUNTING BAR - LH	1	\$ 182.00		
17	FRONT DOOR BOWDEN CABLE	1	\$ 58.00		
18	FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	1	\$ 286.00		
19	FRONT DOOR HANDLE -LH	1	\$ 398.00		
20	FRONT DOOR HANDLE HOUSING - LH	1	\$ 58.00		
SUB TOTAL SPARE PARTS		:	\$ 13,522.00	\$	7,677.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 8625 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	7,677.04
21	REAR DOOR - LH	1	\$ 3,265.00	\$	2,612.00
22	REAR DOOR OUTER SEAL - LH	1	\$ 179.00	\$	142.80
23	BONDING AGENT	1	\$ 51.00	\$	40.56
24	CLEANING SOLUTIO N	1	\$ 74.00	\$	58.96
25	APPLICATOR	1	\$ 9.00		
26	REAR DOOR ATTACHMENT PARTS - LH	1	\$ 252.00		
27	REAR DOOR CATCH - LH	1	\$ 116.00		
28	REAR ALUMINIUM RIM -LH	1	\$ 1,303.00		
29	RUBBER VALVE	1	\$ 4.00		
30	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$	200.00
31	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
32	CAVITY WAX	S/N	\$ 140.00	\$	140.00
33	STONE CHIP	S/N	\$ 180.00	\$	180.00
34	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
35	1/4 GLASS SEALANT	S/N	\$ 100.00	\$	100.00
36	SUNDRIES		\$ 400.00	\$	60.32
TOTAL SPARE PARTS		:	\$ 20,255.00	\$	11,671.68
TOTAL LABOUR CHARGES		:	\$ 18,752.00	\$	13,047.00
GRAND TOTAL		:	\$ 39,007.00	\$	24,718.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-07/12/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT