

Section A - Accident Details

Registration Number	SHB1237Y
Case Reference Number	TAX/08/22/2007
Registration Date	23/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	SUNDARAMOORTHY S/O SIVASAMY
Type of Accident	Head to Rear
Accident Date and Time	5/8/2022 12:00 PM
Accident Reported Date and Time	5/8/2022 1:46 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115838
Special Instruction to ARC, if any	TP/ REAR LEFT PORTION
Prepared Date and Time	5/8/2022 2:38 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$500.00
Total Spray Cost	\$1,974.00	\$440.00
Total Spare Part Cost	\$5,091.76	\$1,835.88
Total Other Cost	\$1,000.00	\$380.00
TOTAL COST	\$9,265.76	\$3,155.88 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / AXA
ARC / Surveyor Sign Off Date	05/08/2022 3:05 PM	08/08/2022 10:55 AM
Signature		
Remarks		resurvey before paint / part by part repair

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2208-0222	Invoice Number	
Quotation Date	18.08.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$1,200.00	\$500.00 ✓
Total Labour	\$1,200.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$428.00	\$220.00 ✓
TO RESPRAY REAR PANEL	\$230.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$230.00	\$0.00
TO RESPRAY TAIL GATE	\$428.00	\$0.00
TO RESPRAY REAR FENDER LH	\$428.00	\$220.00 ✓
TO RESPRAY BUMPER BEAM	\$230.00	\$0.00
Total Spray Painting & Panel Beating	\$1,974.00	\$440.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00 ✓
ISOLATED OF (EV) (NET)	\$150.00	\$150.00 ✓
Total Other Costs	\$1,000.00	\$380.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10328219-SEPP	TAIL GATE ASM-LIFT	0.00	\$1,928.26	0.00	\$0.00	Replace	Not Given
		10103179	HINGE ASM-L/GATE - LH	0.00	\$30.88	0.00	\$0.00	Replace	Not Given
		10103178	HINGE ASM-L/GATE - RH	0.00	\$30.88	0.00	\$0.00	Replace	Not Given
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	30.00	\$530.94	Replace	Replace
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	30.00	\$161.48	Replace	Replace
		10359002	FINISHER-RR BPR - LH	1.00	\$47.42	30.00	\$33.19	Replace	Replace
		10465723	BRACKET ASM-RR BPR FASCIA SI-L	0.00	\$29.85	0.00	\$0.00	Replace	Check
		10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$12.80	0.00	\$0.00	Replace	Check
		10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$46.08	0.00	\$0.00	Replace	Check
		10371766	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$13.20	0.00	\$0.00	Replace	Not Given
		10371768	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$12.90	0.00	\$0.00	Replace	Not Given

X NN
X NN
X NN
✓ DE
✓ CUT
✓ SCR
X } NN
X } NN
X } NN
X }

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/08/2022

User ID : PohSuan

		90004065	CLIP-RR BPR FASCIA	10.00	\$1.24	30.00	\$8.68	Replace	Replace
		10327894	BAR ASM-RR BPR IMP	0.00	\$339.76	0.00	\$0.00	Replace	Check
		10450132	COVER-RR TOW HOOK OPG	0.00	\$6.76	0.00	\$0.00	Replace	Not Given
		10587409	LAMP ASM-TAIL(BODY SI) - LH	1.00	\$764.08	10.00	\$687.67	Replace	Replace
		10587411	LAMP ASM-TAIL(LID SI) - LH	1.00	\$407.68	10.00	\$366.91	Replace	Replace
		10726676	LAMP ASM-RR FOG - LH	1.00	\$36.30	30.00	\$25.41	Replace	Replace
		10345435-SEPP	PANEL-BODY SI OTR-L	1.00	\$1,747.82	100.00	\$0.00	Replace	Repair
			STICKER ELECTRIC (LOGO	1.00	\$21.60	0.00	\$21.60	Replace	Replace
			STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given
			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given
		10376550-WSD	SENSOR-RR PARK DIST CONT	0.00	\$65.00	0.00	\$0.00	Replace	Check
		10885560	EMBLEM ASM-L/GATE (MG5 SW)	0.00	\$21.84	0.00	\$0.00	Replace	Not Given
		10896035	EMBLEM ASM-L/GATE (SW EV)	0.00	\$33.90	0.00	\$0.00	Replace	Not Given
		10935050	EMBLEM ASM-RR LIC PLT (MG)	0.00	\$62.92	0.00	\$0.00	Replace	Not Given
		10562676	PLATE ASM-RR LIC PLT	0.00	\$96.40	0.00	\$0.00	Replace	Not Given
Total					\$6,776.13		\$1,835.88		

√ Nec
X NN
X NN
√ Cra
√ Scr
√ Cra
RX
√ Nec
X
X } NN
X } NN

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,835.88
+ 500.00
+ 820.00
3,155.88