

## Case Details

Case Reference Number : TAX/08/22/2007  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1237Y

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-19002-ID  
 Assigned By : Tan Lee Ge #

Insurance Company Name : AXA Insurance Singapore Pte Ltd  
 Accident Date and Time : 05/08/2022 04:15 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			TAIL GATE ASM-LIFT	1	1,928.26	1,928.26	30.00	1,349.78	Replace	0	0	Not Give	XAN
Standard	Main			HINGE ASM-L/GATE - LH	1	30.88	30.88	30.00	21.62	Replace	0	0	Not Give	XAN
Standard	Main			HINGE ASM-L/GATE - RH	1	30.88	30.88	30.00	21.62	Replace	0	0	Not Give	XAN
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	30.00	530.94	Replace	1	530.94	Replace	de
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	30.00	161.48	Replace	1	161.48	Replace	ent
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	30.00	33.19	Replace	1	33.19	Replace	soe
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-L	1	29.85	29.85	30.00	20.90	Replace	0	0	Check	?XAN
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	30.00	8.96	Replace	0	0	Check	?XAN
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	46.08	30.00	32.26	Replace	0	0	Check	?XAN
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - LH	1	13.20	13.20	30.00	9.24	Replace	0	0	Not Give	XAN
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	1	12.90	12.90	30.00	9.03	Replace	0	0	Not Give	XAN

Total Spare Part Cost	5,091.76	Surveyor Total	1,835.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	5,091.76	Final Sur Total	1,835.88

5/5/22, 10:54 AM

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			CLIP-RR BPR FASCIA	10	1.24	12.40	30.00	8.68	Replace	10	8.68 /	Replace	Re
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	30.00	237.83	Replace	0	0	Check	Xi
Standard	Main			COVER-RR TOW HOOK OPG	1	6.76	6.76	30.00	4.73	Replace	0	0	Not Give	Xm
Standard	Main			LAMP ASM-TAIL(BODY SI) - LH	1	764.08	764.08	10.00	687.67	Replace	1	687.67 /	Replace	Co
Standard	Main			LAMP ASM-TAIL(LID SI) - LH	1	407.68	407.68	10.00	366.91	Replace	1	366.91 /	Replace	So
Standard	Main			LAMP ASM-RR FOG - LH	1	36.30	36.30	30.00	25.41	Replace	1	25.41 /	Replace	CW
Standard	Main			PANEL-BODY SI OTR-L	1	1,747.82	1,747.82	30.00	1,223.47	Replace	1	0	Repair	R
Standard	Main			STICKER ELECTRIC ( LOGO	1	21.60	21.60	0.00	21.60	Replace	1	21.60 /	Replace	m
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xm
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xm
Standard	Main			SENSOR-RR PARK DIST CONT	3	65.00	195.00	30.00	136.50	Replace	0	0	Check	Xm
Standard	Main			EMBLEM ASM-L/GATE ( MG5 SW)	1	21.84	21.84	30.00	15.29	Replace	0	0	Not Give	Xm
Standard	Main			EMBLEM ASM-L/GATE (SW EV )	1	33.90	33.90	30.00	23.73	Replace	0	0	Not Give	Xm
Standard	Main			EMBLEM ASM-RR LIC PLT ( MG )	1	62.92	62.92	30.00	44.04	Replace	0	0	Not Give	Xm
Standard	Main			PLATE ASM-RR LIC PLT	1	96.40	96.40	30.00	67.48	Replace	0	0	Not Give	Xm
Total Spare Part Cost									5,091.76	Surveyor Total		1,835.88		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									5,091.76	Final Sur Total		1,835.88		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	1,200.00	500	
Total:			1,200.00	500.00	

Spray Cost Detail

FBA

SCF

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220	
2	Main	TO RESPRAY REAR PANEL	230.00	0 Xnn	
3	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	230.00	0 Xnn	
4	Main	TO RESPRAY TAIL GATE	428.00	0 Xnn	
5	Main	TO RESPRAY REAR FENDER LH	428.00	220	
6	Main	TO RESPRAY BUMPER BEAM	230.00	0 Xnn	
<b>Total:</b>			<b>1,974.00</b>	<b>440.00</b> /	


**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xnn	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 Xnn	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 Xnn	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	380.00	150	
7	Main	ISOLATED OF (EV) (NET)	150.00	150	
<b>Total:</b>			<b>1,000.00</b>	<b>380.00</b> /	

LK Auto Care and Detailing  
 the Repairer to the following:  
 • To remove damaged parts (during labour)  
 • To apply rust proofing on affected area  
 • To check and reset system function  
 • To test and re-secure reverse sensor system  
 • To replace sundry parts  
 • To wash and vacuum  
 • To apply rust proofing on affected area  
 • To check wiring and system function  
 • To spray paint rear bumper, bumper beam, rear floor side panel LH, rear fender LH, rear panel, tail gate and rear bumper  
 Estimated by Repairer  
 Date:

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,091.76	1,835.88
Total Labour Cost	1,200.00	500.00
Total Spray Painting	1,974.00	440.00
Other	1,000.00	380.00
<b>Overall Total</b>	<b>9,265.76</b>	<b>3,155.88</b>
Lump Sum Repair Option		<input type="checkbox"/>

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Total	0.00	3,155.88
Surveyor Approved Amount		3,155.88
No of Repair Days*	5	3
Remarks	-	resurvey before paint / part by part repair
Surveyor Name		Rasul
Signature		
Survey Date	08/08/2022	

Save Clear

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: