

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC 22007505/Ueq3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMR 5416

at Workshop m/s

RL

of

Insured:

XD 81228

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 78k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

597A

Vehicle: IN / OUT

Date:

Person Contacted:

27A 28167

Date / Time

Action / Instruction

27 10k

have G.I.V

18/8/22 4/5 & 5700 informed Alan.

Veh No:

SMR 5416

Yr Regn:

17/12/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda

Jazz

c.c

1318

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

61508

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK3850LS 212988

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

04/08/22

D.O.I.

5/8/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

4th Ashe

not Adward
date

5/8/22

1/5 \$5700/
5 days.

VEHICLE NO: SMR 541G

1PC	BONNET	no	573.20	\$950.00	—
2PCS	BONNET HINGES @\$65.00	sent		\$130.00	—
1PC	BONNET INSULATOR	no	145.80	\$152.00	—
1PC	BONNET INNER RUBBER	new		\$38.00	—
1PC	BONNET LOCK	new		\$108.00	—
1PC	BONNET BLACK TOP GARNISH	new		\$166.90	—
1PC	FRONT SUPPORT PANEL	sent	525.20	\$560.00	—
1PC	FRONT BUMPER	2e/Torn	538.10	\$650.00	—
2PCS	FRONT BUMPER SIDE RETAINERS @\$35.00	new		\$70.00	—
2PCS	FRONT BUMPER FOG LAMP GARNISHS @105.00	new		\$210.00	X
1PC	FRONT BUMPER REINFORCEMENT	R		\$350.00	X
2PCS	FRONT BUMPER INNER AIR GUIDES @\$80.00	new		\$160.00	X
1PC	FRONT BUMPER LOWER CENTRE GRILLE	new		\$188.00	X
2PCS	FRONT BUMPER LOWER MOULDINGS @\$103.00	new		\$206.00	X
1PC	FRONT BUMPER TOW COVER	new		\$20.00	X
2PCS	HEADLAMPS @\$1850.00	new	725.20 x 2 = 1450.40	\$3,700.00	1450.40
2PCS	HEADLAMP LOWER BRACKETS @\$45.00	new		\$90.00	X
1PC	HORN UNIT	new		\$98.00	X
2PCS	FRONT FENDERS @\$535.00	N/S R 2/5 BUC	425.10	\$1,070.00	170
2PCS	FRONT FENDER INNER SHIELDS @\$95.00	new		\$190.00	X
1SET	FRONT FENDER INNER SHIELD CLIPS	new		\$35.00	X
1PC	FRONT GRILLE	new	282.60	\$620.00	—
1PC	FRONT GRILLE TOP CHROME	new		\$350.00	X
1PC	FRONT 'H' LOGO	new		\$38.00	X
1PC	FRONT GRILLE INNER	new		\$315.00	X
1PC	WIPER GARNISH	new	188.40	\$250.00	—
1PC	FRONT WINDSCREEN	new	1453.90	\$1,488.20	—
1PC	FRONT WINDSCREEN MOULDING	new	(202) 86.00	\$110.80	—
1PC	FRONT WIRE HARNESS	R		\$228.00	X
				\$12,541.90	

S.NETT

1SET	FRONT BUMPER CLIPS	new	\$35.00	30
1PC	FRONT BUMPER LICENCE PLATE	new	\$50.00	X
1BOL	RADIATOR COOLANT	new	\$30.00	X
1BOL	AIR CON OIL	new	\$30.00	X
1SET	BONNET INSULATOR CLIPS	new	\$38.00	30
1PC	FRONT WINDSCREEN SEALANT	new	\$50.00	40
1PC	FRONT WINDSCREEN INNER SEAL	new	\$50.00	40
1PC	FRONT WINDSCREEN SOLAR FILM	new	\$250.00	180

TO CHECK WIRING
 TO DISMANTLE & REPLACED FRONT WINDSCREEN
 TO RESET & REPROGRAMME , DIAGNOSIS SYSTEM
 TO REFILL AIR CON GAS
 TO DISMANTLE & REPLACED FRONT WINDSCREEN
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$150.00	120
11	\$200.00	X
	\$120.00	100
Repehl	\$120.00	X
	\$200.00	60
	\$1,200.00	600
	\$1,500.00	1000
TOTAL	\$16,842.90	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7-6181-60
 207
 4945.28
 320
 1900
 7165.28
 202
 5733