

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0566/2022/EQ
DATE : 8-Jul-22
WIP : 32126

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : GBK 8919 R

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian
3 days - ok - Johnny Boo
31-Oct-22

OWNER'S NAME : MR ROBIN PAITIMUSA
ADDRESS : 18 FLORA DRIVE
#06-32
SINGAPORE 506946
TELEPHONE : HP +65 9654 0129
TYPE OF CLAIM : OD CLAIM
POLICY NO : 2100403389-07
VEHICLE NO : **SKR 4899 Y**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 11/2/2015
ENGINE NO : CZC 217924
CHASSIS NO : WAUZZZ8V1F1054960
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jul-22
PLACE OF ACCIDENT : AT THE JUNCTION OF BEDOK SOUTH AVENUE 1 TURNING TO
UPPER EAST COAST ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 4899 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N	\$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	1,400.00	\$ 500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.		\$	2,000.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	3,872.00	\$ 1,522.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 4899 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,201.00	\$	1,760.80
2	REAR BUMPER FIXING PARTS	1	\$ 201.00		
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00		
4	REAR BUMPER LOCKING MECHANISM	2	\$ 67.00		
5	REAR BUMPER SPOILER	1	\$ 264.00	\$	210.80
6	REAR BUMPER SIDE REINFORCEMENT	1	\$ 642.00		
7	REAR BUMPER BRACKET - LH / RH	2	\$ 30.00		
8	REAR PARKING AID SENSOR	2	\$ 530.00	\$	195.12
9	REAR SEAL RING	4	\$ 10.00		
10	REAR LIGHT REFLECTOR - LH	1	\$ 46.00	\$	36.48
11	EXHAUST TAIL PIPE CHROME TRIM - LH	1	\$ 128.00		
12	SUNDRIES		\$ 300.00		
TOTAL SPARE PARTS		:	\$ 4,455.00	\$	2,203.20
TOTAL LABOUR CHARGES		:	\$ 3,872.00	\$	1,522.00
GRAND TOTAL		:	\$ 8,327.00	\$	3,725.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-05/10/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT