

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0656/2022/EQ
DATE : 3-Aug-22
WIP : 35477

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : VOESTALPINE HIGH PERFORMANCE METALS
ADDRESS : 23 NEWTON ROAD
#23-05
SINGAPORE 307955
TELEPHONE : HP +65 91784837
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070164200
VEHICLE NO : **SMW 4249 Z**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI S-TRONIC
MODEL YEAR : 20/11/2020
ENGINE NO : DEM 026164
CHASSIS NO : WAUZZZF52MA007422
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Jul-22
PLACE OF ACCIDENT : THAI TEMPLE, KAMPONG, TIONG BAHRU

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 4249 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00 500	
3	TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR END PANELLING.	\$ 3,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,952.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 4249 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,609.00	✓	
2	REAR BUMPER SECURING STRIP - UPPER <i>nee</i>	1	\$ 125.00	✓	
3	REAR BUMPER SECURING STRIP - LOWER <i>nee</i>	1	\$ 249.00	✓	
4	REAR BUMPER SPOILER <i>lit</i>	1	\$ 276.00	✓	
5	REAR BUMPER BRACKET - LH <i>nee</i>	1	\$ 228.00	+	
6	REAR BUMPER REFLECTOR - LH / RH <i>nee</i>	2	\$ 96.00	+	
7	REAR BUMPER OUTER TAIL LIGHT - LH <i>could</i>	1	\$ 1,269.00	✓	
8	REAR BUMPER OUTER TAIL LIGHT TRIM - LH <i>nee</i>	1	\$ 34.00	+	
9	REAR BUMPER GUIDE SECTION - LH / RH - UPPER ?	2	\$ 52.00	?	
10	REAR BUMPER GUIDE SECTION - LH - LOWER ?	1	\$ 49.00	?	
11	REAR BUMPER HOLDING STRAP - LH ?	1	\$ 94.00	?	
12	GUIDE SECTION PIN ?	1	\$ 3.00	?	
13	REAR BUMPER REINFORMENT BEAM <i>nee</i>	1	\$ 1,131.00	+	
14	REAL BUMPER SEAL <i>nee</i>	2	\$ 32.00	+	
15	REAR PARKING AID SENSOR - INNER / OUTER <i>nee</i>	2	\$ 531.00	+	
16	REAR PARKING AID SENSOR - SIDE <i>nee</i>	1	\$ 266.00	+	
17	REAR PARKING AID SEAL RING <i>nee</i>	4	\$ 10.00	+	
18	REAR FENDER TRIM <i>nee</i>	1	\$ 75.00	+	
19	REAR EXHAUST TAIL PIPE CHROME TRIM - LH <i>lit</i>	1	\$ 383.00	✓	
20	AERIAL RETAINER - LH <i>nee</i>	1	\$ 29.00	+	
21	TELEPHONE AERIAL <i>nee</i>	1	\$ 192.00	+	
22	SUNDRIES ?		\$ 400.00	?	
TOTAL SPARE PARTS			\$ 8,133.00		
TOTAL LABOUR CHARGES			\$ 5,952.00		
GRAND TOTAL			\$ 14,085.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *05/08/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT