

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Veron.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 4249 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. <u>TO REPAIR LHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.</u>	\$ 2,400.00 500 + 250	sls.
3	TO RESPRAY REAR BUMPER, <u>LHS REAR FENDER, REAR END PANELLING.</u>	\$ 3,000.00 550 + 550.	sls.
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>5,952.00</u>	

+ 1 day repair day

Adrian Li
 Resurveyed sls.

To add 1 day for the repairs to the rear fender.

Car-in

30/8/12

wip-35477

PREMIUM AUTOMOBILES

Benz



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIR - Admin

- 3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 4249 Z

V-GER 1718

V-SK 1718

AIR SK 1718

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,609.00	✓
2	REAR BUMPER SECURING STRIP - UPPER <i>nee</i>	1	\$ 125.00	✓
3	REAR BUMPER SECURING STRIP - LOWER <i>nee</i>	1	\$ 249.00	✓
4	REAR BUMPER SPOILER <i>at</i>	1	\$ 276.00	✓
5	REAR BUMPER BRACKET - LH <i>nee</i>	1	\$ 228.00	+
6	REAR BUMPER REFLECTOR - LH / RH <i>nee</i>	2	\$ 96.00	+
7	REAR BUMPER OUTER TAIL LIGHT - LH <i>could</i>	1	\$ 1,269.00	✓
8	REAR BUMPER OUTER TAIL LIGHT TRIM - LH <i>nee</i>	1	\$ 34.00	+
9	REAR BUMPER GUIDE SECTION - LH / RH - UPPER <i>could</i>	2	\$ 52.00	✓
10	REAR BUMPER GUIDE SECTION - LH - LOWER <i>could</i>	1	\$ 49.00	✓
11	REAR BUMPER HOLDING STRAP - LH ?	1	\$ 94.00	?
12	GUIDE SECTION PIN ?	1	\$ 3.00	?
13	REAR BUMPER REINFORMENT BEAM <i>nee</i>	1	\$ 1,131.00	+
14	REAL BUMPER SEAL <i>nee</i>	2	\$ 32.00	+
15	REAR PARKING AID SENSOR - INNER / OUTER <i>nee</i>	2	\$ 531.00	+
16	REAR PARKNG AID SENSOR - SIDE <i>nee</i>	1	\$ 266.00	+
17	REAR PARKING AID SEAL RING <i>nee</i>	4	\$ 10.00	+
18	REAR FENDER TRIM <i>nee</i> - vert trim <i>could</i>	1	\$ 75.00	✓
19	REAR EXHAUST TAIL PIPE CHROME TRIM - LH <i>at</i>	1	\$ 383.00	✓
20	AERIAL RETAINER - LH <i>nee</i>	1	\$ 29.00	+
21	TELEPHONE AERIAL <i>nee</i>	1	\$ 192.00	+
22	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS			\$ 8,133.00	
TOTAL LABOUR CHARGES			\$ 5,952.00	
GRAND TOTAL			\$ 14,085.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.