

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0651/2022/EQ
DATE : 2-Aug-22
WIP : 35766

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

7 days exclude 1 Sunday

Johnny Boo 29 Nov 22

OWNER'S NAME : MR. CHAN YU HUAI
ADDRESS : 7 PINE GROVE
#07-04, ASTOR GREEN
SINGAPORE 597592
TELEPHONE : HP +65 96966120
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070153369-01
VEHICLE NO : **SLS 3121 Y**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFSI
MODEL YEAR : 5/11/2020
ENGINE NO : CZD C04268
CHASSIS NO : WAUZZZF38M1018780
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Jul-22
PLACE OF ACCIDENT : ALONG AYE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 3121 Y - FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,000.00	\$	2,050.00
TOTAL LABOUR CHARGES (FRONT)		:	\$ 7,280.00	\$	3,530.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 3121 Y - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>C./F</i>		\$ 3,530.00
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	\$ 500.00
3	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,000.00	\$ 1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES (REAR)		: \$ 14,632.00	\$ 6,082.00
GRAND TOTAL FRONT AND REAR		\$ 21,912.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	2	\$ 1,585.00	\$	1,267.60
2	FRONT BUMPER FIXING PARTS	1	\$ 433.00		
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 66.00		
4	FRONT BUMPER CENTER TRIM	1	\$ 396.00		
5	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 242.00		
6	FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 58.00		
7	FRONT BUMPER LOWER GRILLE COVER - CENTER	1	\$ 58.00		
8	FRONT BUMPER LOWER CLOSING ELEMENT	1	\$ 212.00		
9	FRONT BUMPER SPOILER	1	\$ 850.00		
10	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00		
11	FRONT BUMPER AIR GUIDE GRILLE TRIM - RH	1	\$ 182.00		
12	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 29.00		
13	RADIATOR GRILLE	1	\$ 2,135.00	\$	1,708.00
14	REAR STRIKER PLATE	1	\$ 271.00		
15	COVER CAP	1	\$ 256.00		
16	BRACKET	1	\$ 46.00		
17	SECURING PLATE	1	\$ 37.00		
18	FRONT COVER	1	\$ 271.00	\$	216.80
19	FRONT CAMERA	1	\$ 1,264.00		
20	FRONT BUMPER FOAM FILLER PIECE	1	\$ 114.00		
SUB TOTAL SPARE PARTS		:	\$ 8,676.00	\$	3,192.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	
21	FRONT BUMPER CARRIER	1	\$	974.00	
22	FRONT BUMPER GUIDE SECTION - RH	1	\$	43.00	
23	FRONT BUMPER TOP COVER	1	\$	137.00	\$ 109.60
24	CAUTION SIGN STICKER	1	\$	16.00	\$ 12.40
25	AIR CONDITIONER STICKER	1	\$	9.00	\$ 6.64
26	HORN SIGNAL LOW TONE - RH	1	\$	146.00	
27	HORN BRACKET - RH	1	\$	25.00	
28	BONNET	1	\$	3,695.00	\$ 2,956.00
29	BONNET HINGE - LH / RH	2	\$	162.00	
30	BONNET ATTACHMENT PARTS	1	\$	309.00	
31	BONNET STRIKER - RH	1	\$	123.00	
32	BONNET SOUND ABSORBER	1	\$	244.00	
33	EXHAUST IMPACT PROTECTION - CENTER	1	\$	31.00	\$ 24.24
34	BONNET LID LOCK MICRO-SWITCH - RH	1	\$	228.00	
35	BOWDEN CABLE - CENTER	1	\$	64.00	
36	BONNET RELEASE ELEMENT	1	\$	65.00	
37	BONNET RELEASE LEVER	1	\$	16.00	
38	BOWDEN CABLE COVER	1	\$	11.00	
39	FRONT PARKING AID SENSOR - LH / RH	2	\$	531.00	
40	FRONT PARKING AID SEAL RING	4	\$	10.00	
SUB TOTAL SPARE PARTS		:	\$	6,839.00	\$ 6,301.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	6,301.28
41	HEADLIGHT MAIN BEAM MOUNTING - RH	1	\$ 132.00	\$	105.20
42	HEADLIGHT - RH	1	\$ 5,952.00		
43	LIFT CYLINDER - RH	1	\$ 231.00		
44	LIFT CYLINDER HOSE	1	\$ 92.00		
45	FRONT RADIATOR AIR GUIDE - RH	1	\$ 43.00		
46	FRONT RADIATOR AIR GUIDE - UPPER	1	\$ 48.00		
47	FRONT TEMPERATURE SENSOR HOLDER	1	\$ 9.00		
48	FRONT WHEEL COVER - LH / RH	2	\$ 1,132.00	\$	904.80
22	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
SUB TOTAL SPARE PARTS		:	\$ 7,699.00	\$	7,371.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - REAR

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 7,371.28
1	REAR BUMPER	1	\$ 1,738.00	\$ 1,390.40
2	REAR BUMPER SPOILER	1	\$ 510.00	\$ 408.00
3	REAR BUMPER SUPPORT - CENTER	1	\$ 108.00	
4	REAR BUMPER GRILLE - RH	1	\$ 170.00	
5	REAR PARKING AID SENSOR SUPPORT - RH	1	\$ 28.00	
6	REAR BUMPER ADAPTER - RH	1	\$ 95.00	
7	REAR BUMPER BRACKET	1	\$ 53.00	
8	REAR BUMPER REFLECTOR - RH	1	\$ 46.00	
9	REAR OPENING BOOT LID CONTROL UNIT	1	\$ 484.00	
10	AERIAL ACCESS KEY	1	\$ 79.00	
11	REAR BUMPER SHOCK ABSORBER	1	\$ 95.00	
12	REAR BUMPER CARRIER	1	\$ 693.00	
13	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 64.00	
14	REAR BUMPER GUIDE SECTION - RH	1	\$ 71.00	
15	REAR PARKING AID SENSOR - LH / RH	2	\$ 531.00	
16	REAR PARKING AID SEAL RING	4	\$ 10.00	
17	ADHESIVE TAPE	1	\$ 21.00	
18	REAR AUDI EMBLEM	1	\$ 144.00	
19	"Q3" INSCRIPTION CHROME	1	\$ 104.00	
20	UNDERBODY TRIM - RH	1	\$ 58.00	
SUB TOTAL SPARE PARTS		:	\$ 5,102.00	\$ 9,169.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 9,169.68
21	REAR WHEEL COVER - LH / RH	2	\$ 1,132.00	\$ 904.80
23	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS - FRONT AND REAR			\$ 29,848.00	\$ 10,074.48
TOTAL LABOUR CHARGES			\$ 21,912.00	\$ 6,082.00
GRAND TOTAL FRONT AND REAR			\$ 51,760.00	\$ 16,156.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/11/22