

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0651/2022/EQ
DATE : 2-Aug-22
WIP : 35766

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. CHAN YU HUAI
ADDRESS : 7 PINE GROVE
#07-04, ASTOR GREEN
SINGAPORE 597592
TELEPHONE : HP +65 96966120
TYPE OF CLAIM : ~~THIRD PARTY CLAIM~~ *OD claim.*
POLICY NO : 2070153369-01
VEHICLE NO : **SLS 3121 Y**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFSI
MODEL YEAR : 5/11/2020
ENGINE NO : CZD C04268
CHASSIS NO : WAUZZZF38M1018780
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Jul-22
PLACE OF ACCIDENT : ALONG AYE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 3121 Y - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,000.00	2050 wheel Arc = 200 x 2 = 400 3 x 550 = 1650 <u>2050</u>
TOTAL LABOUR CHARGES (FRONT)		: \$ 7,280.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 3121 Y - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 2,800.00 500	
3	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS. ✓ spoiler ✓ ✓	\$ 4,000.00 1500	Wheel Arc = 200 x 2 = 400
4	TO CARRY OUT DIAGNOSTIC CHECK. ✓	S/N \$ 192.00 ✓	550 x 2 = 1100 1500
TOTAL LABOUR CHARGES (REAR)		: \$ 14,632.00	
GRAND TOTAL FRONT AND REAR		\$ 21,912.00	

Marking and upload photos

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Deformed</i>	2	\$ 1,585.00	✓	1267.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 433.00	+	
3	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	1	\$ 66.00	X	
4	FRONT BUMPER CENTER TRIM <i>new</i>	1	\$ 396.00	+	
5	FRONT BUMPER LOWER GRILLE - CENTER <i>new</i>	1	\$ 242.00	+	
6	FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 58.00	+	
7	FRONT BUMPER LOWER GRILLE COVER - CENTER <i>new</i>	1	\$ 58.00	+	
8	FRONT BUMPER LOWER CLOSING ELEMENT <i>new</i>	1	\$ 212.00	+	
9	FRONT BUMPER SPOILER <i>Regis</i>	1	\$ 850.00	+	
10	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	+	
11	FRONT BUMPER AIR GUIDE GRILLE TRIM - RH	1	\$ 182.00	+	
12	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 29.00	+	
13	RADIATOR GRILLE <i>built</i>	1	\$ 2,135.00	✓	1708.00
14	REAR STRIKER PLATE <i>new</i>	1	\$ 271.00	X	
15	COVER CAP <i>new</i>	1	\$ 256.00	+	
16	BRACKET	1	\$ 46.00	+	
17	SECURING PLATE	1	\$ 37.00	+	
18	FRONT COVER <i>new</i> <i>CRA</i>	1	\$ 271.00	✓	216.80
19	FRONT CAMERA	1	\$ 1,264.00	X	
20	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 114.00	X	
SUB TOTAL SPARE PARTS		:	\$ 8,676.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER CARRIER <i>Ne n</i>	1	\$ 974.00	X	
22	FRONT BUMPER GUIDE SECTION - RH <i>Ne n</i>	1	\$ 43.00	X	
23	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 137.00	+✓	109.60
24	CAUTION SIGN STICKER <i>Nec</i>	1	\$ 16.00	+✓	12.40
25	AIR CONDITIONER STICKER	1	\$ 9.00	+✓	6.64
26	HORN SIGNAL LOW TONE - RH <i>Ne n</i>	1	\$ 146.00	+	
27	HORN BRACKET - RH <i>Ne n</i>	1	\$ 25.00	+	
28	BONNET <i>Dented</i>	1	\$ 3,695.00	✓	2956.00
29	BONNET HINGE - LH / RH	2	\$ 162.00	+	
30	BONNET ATTACHMENT PARTS <i>Ne n</i>	1	\$ 309.00	+	
31	BONNET STRIKER - RH	1	\$ 123.00	+	
32	BONNET SOUND ABSORBER	1	\$ 244.00	+	
33	EXHAUST IMPACT PROTECTION - CENTER <i>Ne n</i>	1	\$ 31.00	✓	24.24
34	BONNET LID LOCK MICRO-SWITCH - RH <i>Ne n</i>	1	\$ 228.00	+	
35	BOWDEN CABLE - CENTER	1	\$ 64.00	+	
36	BONNET RELEASE ELEMENT <i>Ne n</i>	1	\$ 65.00	+	
37	BONNET RELEASE LEVER	1	\$ 16.00	+	
38	BOWDEN CABLE COVER	1	\$ 11.00	+	
39	FRONT PARKING AID SENSOR - LH / RH <i>Ne n</i>	2	\$ 531.00	+	
40	FRONT PARKING AID SEAL RING <i>Nec</i>	4	\$ 10.00	+	
SUB TOTAL SPARE PARTS			\$ 6,839.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - FRONT

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	HEADLIGHT MAIN BEAM MOUNTING - RH <i>cracked</i>	1	\$ 132.00	☒	105.20
42	HEADLIGHT - RH <i>Rem</i>	1	\$ 5,952.00	☒	
43	LIFT CYLINDER - RH <i>Rem</i>	1	\$ 231.00	☒	
44	LIFT CYLINDER HOSE <i>Rem</i>	1	\$ 92.00	☒	
45	FRONT RADIATOR AIR GUIDE - RH <i>Rem</i>	1	\$ 43.00	☒	
46	FRONT RADIATOR AIR GUIDE - UPPER <i>Rem</i>	1	\$ 48.00	☒	
47	FRONT TEMPERATURE SENSOR HOLDER <i>Rem</i>	1	\$ 9.00	☒	
48	FRONT WHEEL COVER - LH / RH <i>Rem</i>	2	\$ 1,132.00	☒	904.80
22	FRONT NO PLATE <i>Rem</i>	S/N	\$ 60.00	☒	60.00
SUB TOTAL SPARE PARTS		:	\$ 7,699.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - REAR

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Dehd</i>	1	\$ 1,738.00 ✓		1390.40
2	REAR BUMPER SPOILER <i>Dehd</i>	1	\$ 510.00 ✓		408.00
3	REAR BUMPER SUPPORT - CENTER <i>XNN</i>	1	\$ 108.00 ✗		
4	REAR BUMPER GRILLE - RH <i>Dehd</i>	1	\$ 170.00 ✗		
5	REAR PARKING AID SENSOR SUPPORT - RH <i>Dehd</i>	1	\$ 28.00 ✗		
6	REAR BUMPER ADAPTER - RH <i>Dehd</i>	1	\$ 95.00 ✗		
7	REAR BUMPER BRACKET <i>Dehd</i>	1	\$ 53.00 ✗		
8	REAR BUMPER REFLECTOR - RH <i>Dehd</i>	1	\$ 46.00 ✗		
9	REAR OPENING BOOT LID CONTROL UNIT <i>Dehd</i>	1	\$ 484.00 ✗		
10	AERIAL ACCESS KEY <i>Dehd</i>	1	\$ 79.00 ✗		
11	REAR BUMPER SHOCK ABSORBER <i>XNN</i>	1	\$ 95.00 ✗		
12	REAR BUMPER CARRIER <i>XNN</i>	1	\$ 693.00 ✗		
13	REAR BUMPER HOLDING STRAP - LH / RH <i>XNN</i>	2	\$ 64.00 ✗		
14	REAR BUMPER GUIDE SECTION - RH <i>XNN</i>	1	\$ 71.00 ✗		
15	REAR PARKING AID SENSOR - LH / RH <i>Dehd</i>	2	\$ 531.00 ✗		
16	REAR PARKING AID SEAL RING <i>Dehd</i>	4	\$ 10.00 ✗		
17	ADHESIVE TAPE <i>Dehd</i>	1	\$ 21.00 ✗		
18	REAR AUDI EMBLEM <i>Dehd</i>	1	\$ 144.00 ✗		
19	"Q3" INSCRIPTION CHROME <i>Dehd</i>	1	\$ 104.00 ✗		
20	UNDERBODY TRIM - RH <i>Dehd</i>	1	\$ 58.00 ✗		
SUB TOTAL SPARE PARTS		:	\$ 5,102.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 3121 Y - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR WHEEL COVER - LH / RH <i>ok</i>	2	\$ 1,132.00	✓ 904.80
23	SUNDRIES <i>2NN</i>		\$ 400.00	X
TOTAL SPARE PARTS - FRONT AND REAR		:	\$ 29,848.00	
TOTAL LABOUR CHARGES		:	\$ 21,912.00	
GRAND TOTAL FRONT AND REAR		:	\$ 51,760.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
05/08/22

Not Authorized, 07 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT