

Date: 05/08/2022

To: Motor Claims Department
EQ Insurance

RE: Estimate repair cost of SKS8861Z

Your Insured: GBF1091A

Dear Sir/Madam,

Vehicle No: SKS8861Z

Make Model: Toyota Wish

Date of accident: 04-08-2022

We are pleased to quote you the repair cost for the above-mentioned vehicle:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary Parts

Qty	Description	Unit Price	TOTAL
1	Rear bumper <i>Dent</i>		\$ 698.30
2	Rear bumper side retainers <i>SV</i>	58.90	\$ 117.80
1	Rear bumper reflector (RH) <i>SV</i>		\$ 98.60
1	Rear bumper bracket (RH) <i>SV Dent</i>		\$ 185.20
2	Rear tail-lamps <i>o/s many crack 4/5 H</i>	411.70	654.20 \$ 1,308.40
1	Rear end panel <i>Dent</i>	536.00	\$ 785.10
1	Bootlid <i>Buc</i>		\$ 1,245.10
1	Bootlid inner garnish <i>many crack</i>		\$ 245.80
1	Weather-stripe <i>defunct H</i>		\$ 156.20
1	Bootlid upper lock <i>Don</i>		\$ 342.10
1	Bootlid lower lock <i>key</i>		\$ 124.90
2	Bootlid lamps <i>o/s broken 4/5 H</i>	387.50	543.20 \$ 1,086.40
1	Bootlid outer chrome <i>crack</i>		\$ 389.30
1	Toyota Logo <i>H</i>		\$ 69.30
1	Numbers plate with holder <i>st</i>	SH 45.00	\$ 60.00
1	Rear windscreen <i>shaded</i>		\$ 630.20
1	Rear wiper motor <i>H</i>		\$ 389.20
1	Rear wiper blade <i>H</i>		\$ 78.20
1	Reverse sensors <i>Don</i>		\$ 200.00
1	Spare tyre board <i>H</i>		\$ 768.10
1	Rear right fender <i>key Dent</i>		\$ 987.20
1	Spare tyre cover <i>H</i>		\$ 123.20
1	Rear Indash Camera <i>SV</i>		\$ 400.00
Sub-total before discount			\$ 10,488.60
Parts percentage discount 25%			\$ 2,622.15
PARTS TOTAL			\$ 7,866.45
LABOUR CHARGES & MISC			
1	Labour to dismantle & replaced the rear bumper, rear end panel, bootlid and all accident damaged parts		\$ 1,200.00
2	Labour to putty & spray painting on the accident damaged parts & replaced parts		\$ 900.00
3	To provide under-coating		\$ 60.00
4	Labour for checking of the bumper, bootlid & all wiring		\$ 60.00
5	Labour to replace rear windscreen		\$ 120.00
LABOUR TOTAL			\$ 2,340.00
LABOUR & PARTS TOTAL			\$ 10,206.45
Parts 6239.30 25% 4679.47 245.00 SH 200.00 Leas 1690.00 6614.47 5,300/-			

Regards,