

Success United Pte Ltd (Co.Reg.No.200402570G)2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

Veron.

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU220089
Policy No:	SP2000683520-01	Date of Loss:	03/08/2022
Vehicle Reg. No.:	SLT7798M	Driveable?	
Driver Age/Info:	51 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Law Johnny	Contact No:	+6594560564
Driver:	Law Johnny		
Make/Model:	MERCEDES-BENZ GLC250D, 2.1 4MATIC (A)	Vehicle Reg. Date:	05/12/2017
Vehicle Colour:	Blue		
Engine No:	65192134164018	Chassis No:	WDC2539092F285839
Odometer:	84173 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	18,086.30
Miscellaneous Items	0.00
Labour	1,880.00
Paintwork Labour	1,000.00
Towing	0.00
Calculated Gross Total (S\$)	20,966.30
- Excess (S\$)	300.00
(S\$)	20,666.30
+ GST 7.00% (S\$)	1,446.64
Nett Amount (S\$)	22,112.94

This claim is handled by: **TEO WEE KEONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

48		*FENDER INNER LINER CLIPS	Ne	0	0.00	*40.00 FS	-
49	1	*FRT NO. PLATE W/FRAME	missing	0	0.00	*40.00 FS	-
50	1	*FRT FENDER INNER LINER RH (FRT)	new	0.00	0.00	*130.00 F	+
51	1	*FRT FENDER INNER LINER RH (REAR)	new	0.00	0.00	*85.00 F	+

F=Franchise part, S=SpcNett.

Sub Total (\$\$)	16,453.00
+ Margin on L,N Items 10.00% (\$\$)	1,633.30
Total Parts (\$\$)	18,086.30

Success United Pte Ltd/SLT7798M/04/08/2022 18:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary

Completed

1. Frt Bonnet Insulator \$185 ✓
2. Frt Fender Guard LH end \$155 ✓
3. Bonnet Line Fastener \$15 ✓

kd

Supplementary.

Adrian Ly

12/08/22

Revised slip.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2022)**Parts:** 143 MERCEDES-BENZ GLC250D 2.1 4MATIC (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Success United Pte Ltd/SLT7798M/12/08/2022 12:05**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET INSULATOR <i>coupled.</i>	0.00	0.00	✓ *190.00 F
2	1		*FRT FENDER GUARD LH <i>2nd.</i>	0.00	0.00	✓ *155.00 F
3	1		*BONNET LINE FASTENER <i>2nd</i>	0.00	0.00	✓ *15.00 F
F=Franchise part.						
Sub Total (S\$)						360.00
+ Margin on L,N Items 10.00% (S\$)						36.00
Total Parts (S\$)						396.00

Success United Pte Ltd/SLT7798M/12/08/2022 12:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Adm Lj
12/08/22
Resigned H.S.