



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM22007518/Upa3q2 Date: 18/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 5186D	Veh. Inspected	SLA 1120H
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S2M048AL	Excess (\$)	0.00
Assign From		Assign Date	08/08/2022
2. Vehicle Particulars & Condition			
Make & Model	AUDI A6 (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WAUZZZ4G2GN061952	Colour	BLACK
Odometer	201202 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/40 R19	GOODYEAR	7 mm
L/H Front Tyre	255/40 R19	GOODYEAR	7 mm
R/H Rear Tyre	235/40 R19	GOODYEAR	7 mm
L/H Rear Tyre	235/40 R19	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/08/2022	Inspection Date	08/08/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	