



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

VERON

ESTIMATE OF REPAIR

Veh# SJL8048D

Model:

TOYOTA ~~ALTIS~~ ^{Vios}

Accident Date 7/8/2022

12/12/2008 11/12/2023

Location :LOR CHUAN TOWARDS BOUNDARY ROAD

3P: SJW40U (GREAT AMERICA)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Distorted</i>	568.20	✓	
2	10 pcs	Front bumper clips <i>new</i>		40.00	✓
3	1 pc	Front bumper grille (Lower) <i>Distorted</i>	196.20	✓	
4	1 pc	Front bumper enforcement <i>Best</i>	206.20	✓	
5	1 pc	Front bumper insulator <i>Distorted</i>	190.20	✓	
6	2 pcs	Front bumper o/s & n/s retainer <i>ZH Paayid</i>	182.00	38	
7	1pc	Front bumper n/s fog lamp garnish <i>Delnd</i>	88.60	✓	
8	1 pc	Front grille <i>blend</i>	286.20	✓	
9	4 pcs	Front grille clips <i>new</i>		16.00	✓
10	1 pc	Front emblem <i>new</i>	70.40	✓	
11	1 pc	Front bonnet <i>Repair</i>	967.50	+	
12	1 pc	Front bonnet lock (lower) <i>new</i>	206.20	+	
13	2 pcs	Front bonnet o/s & n/s hinges <i>new</i>	188.20	+	
14	1 pc	Front bonnet insulator <i>ZMP</i>	269.20	+	
15	12 pcs	Front bonnet insulator clips <i>new</i>		48.00	+
16	1 pc	Front support panel assy <i>Blend</i>	988.20	652	
17	1 pc	Front support panel bracket <i>Best</i>	92.00	✓	
18	2 pcs	Front o/s & n/s head lamp <i>N/S blend</i>	809.20	404.60	
19	4 pcs	Front o/s & n/s head lamp clips <i>new</i>		24.00	10
20	1 pc	Front n/s fender <i>Distorted</i>	406.20	✓	
21	1 pc	Front n/s fender wheel guard <i>Delnd</i>	226.20	✓	
22	9 pcs	Front n/s fender wheel guard clips <i>new</i>		32.00	✓
23	1 pc	Front n/s fender inner panel <i>Repair</i>	682.40	+	
24	1 pc	Front n/s chassis frame outer <i>Repair</i>	322.40	+	
25	1 pc	Front n/s fender VVTI emblem <i>new</i>	62.20	✓	
26	1 pc	Front windscreen <i>cracked</i>	1,070.20	✓	
27	1 pc	Front windscreen sealant <i>ZMP</i>		80.00	60
28	1 pc	Front windscreen lower seal <i>new</i>	169.20	✓	
29	1 pc	Front windscreen inner seal		60.00	30
30	1 pc	Front windscreen washer tank <i>ZMP</i>	306.20	X	
31	1 pc	Front windscreen washer tank motor <i>ZMP</i>	206.20	+	
32	1 pc	Air cond condenser <i>new</i>	897.40	X	
33	2 pcs	Air cond condenser pipe <i>new</i>	440.20	+	
34	4 pcs	Air cond condenser mounting (Upper & Lower) <i>new</i>	206.20	X	

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SJL8048D
 ident Date : 7/8/2022
 Location : LOR CHUAN TOWARDS BOUNDARY ROAD

Model: TOYOTA ALTIS
 12/12/2008 - 11/12/2023
 3P: SJW40U (GREAT AMERICAN)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front under cover <i>3AP</i>	159.10	<i>x</i>	
2	10 pcs	Front under cover clips <i>3AP</i>		40.00	<i>x</i>
3	1 pc	Front air cleaner box <i>checked</i>	540.20	<i>477</i>	
4	1 pc	Front radiator fan assembly <i>checked</i>	670.20	<i>235</i>	
5	1 pc	Front n/s rim <i>3AP</i>		600.00	<i>x</i>
6	1 pc	Front n/s tyre <i>3AP</i>		150.00	<i>x</i>
Sub Total:			1,369.50	790.00	0.00
			25%	0%	10%
After Less %:			1,027.13	790.00	0.00
Total:			1,817.13		
After Less 20%:			1,453.70		

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)

712
 Supplementary: 534



☎ 8778 1999
 24 hr accident call

