

ASS. REC. BY: Marcus

REF:

CS/ASM22007525/Ucy3

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

11A 843003

Date / Time

Action / Instruction

Rep 166.

SGF2882T 3938H No 2016 model from SG Cement

15/8/22 4/5 @ 6000 informed Ken (Red #18,543.05 / 76%)  
5 days

Veh No: SGF2882T

Yr Regn:

29/03/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota RAV4 premium 1987

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

78606

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTMDEREV40D100817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

05/08/22

D.O.I.

08/08/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

# SPEEDWERKZ PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 96195936 / [info@speedwerkz.biz](mailto:info@speedwerkz.biz)

VEHICLE NUMBER: SGF2882T

MAKE & MODEL: TOYOTA RAV4

DOA: 05/08/2022

CLAIM TYPE: TP CLAIM

not allocated  
all  
new  
8/8/22  
1/5 & 6000  
5 days.  
submit to us

## ESTIMATION QUOTE

| PARTS                                  | QTY | PRICE (\$)  | REMARKS   |
|----------------------------------------|-----|-------------|-----------|
| Rear boot cover 1615-20                | 1   | \$ 1,740.80 | 20/But ✓  |
| Rear boot cover emblem ( TOYOTA )      | 1   | \$ 95.00    | Rec ✓     |
| Rear boot lock 542-10                  | 1   | \$ 848.50   | 20/shot ✓ |
| Rear boot lock catch                   | 1   | \$ 56.90    | 11 X      |
| Rear boot centre garnish               | 1   | \$ 215.60   | 11 X      |
| Rear boot cover lower garnish          | 1   | \$ 278.50   | Del/70m ✓ |
| Rear boot centre logo                  | 1   | \$ 96.50    | 11 X      |
| Rear boot absorber @ 677.50            | 2   | \$ 1,355.00 | 11 X      |
| Rear boot inner board                  | 1   | \$ 605.10   | 11 X      |
| Rear boot reflector lamp @424.40       | 2   | \$ 848.80   | 11 X      |
| Rear boot number plate lamp @95.20     | 2   | \$ 190.40   | 11 X      |
| Rear boot hinge @ 106.30               | 2   | \$ 212.60   | 11 X      |
| Rear boot rubber                       | 1   | \$ 325.30   | 7m ✓      |
| Rear boot emblem ( RAV4 )              | 1   | \$ 92.50    | Rec ✓     |
| Rear tail lamp @ 632.50                | 2   | \$ 1,265.00 | 11 X      |
| Rear tail lamp panel @219.80           | 2   | \$ 439.60   | 11 X      |
| Rear end penal 899-10                  | 1   | \$ 989.50   | 20 ✓      |
| Rear end penal top garnish             | 1   | \$ 195.10   | 7m ✓      |
| Rear spare tyre panel                  | 1   | \$ 857.40   | R X       |
| Rear spare tyre panel tool tray sponge | 1   | \$ 607.40   | 11 X      |
| Rear spare tyre panel top cover board  | 1   | \$ 231.90   | 11 X      |
| Rear fender @ 1109.80                  | 2   | \$ 2,219.60 | 11 X      |
| Rear fender inner trim @738            | 2   | \$ 1,476.00 | 11 X      |
| Rear fender shield @110.30             | 2   | \$ 220.60   | 11 X      |
| Rear bumper 866-01                     | 1   | \$ 1,050.20 | Dis ✓     |
| Rear bumper side retainer @ 60.80      | 2   | \$ 121.60   | But ✓     |
| Rear bumper towing cover @86.50        | 1   | \$ 173.00   | 11 X      |
| Rear bumper reflector @195.30          | 2   | \$ 390.60   | 6ra ✓     |

|                                    |   |           |                 |
|------------------------------------|---|-----------|-----------------|
| Rear bumper bracket @85.60         | 2 | \$ 173.00 | 11X             |
| Rear bumper screw nut cover @53.50 | 2 | \$ 107.00 | 11X             |
| Rear bumper pad lower              | 1 | \$ 235.90 | Dis ✓           |
| Rear bumper diffuser               | 1 | \$ 425.20 | Dis ✓           |
| Rear bumper beam                   | 1 | \$ 425.50 | Dis ✓           |
| Rear exhaust silencer box          | 1 | \$ 996.30 | 11X             |
| Rear exhaust heat insulation panel | 1 | \$ 265.20 | 11X             |
| Reversing sensor @235              | 4 | \$ 940.00 | short 2 pcs 470 |
| Reversing sensor hardness wire     | 2 | \$ 255.00 | 11X             |

Rever

25% Less 20%  
Sub Total \$ 18,918.09

| SPECIAL NETT ITEMS                  | QTY | PRICE (\$) | REMARKS  |
|-------------------------------------|-----|------------|----------|
| Rear boot insulator @7              | 12  | \$ 84.00   | 11X      |
| Rear end panel sealant              | 1   | \$ 100.00  | 11 50    |
| Rear end panel top garnish clips @7 | 8   | \$ 56.00   | 11 X     |
| Rear fender inner garnish clips @7  | 20  | \$ 140.00  | 11 X     |
| Rear number plate                   | 1   | \$ 45.00   | 11 X     |
| Rear winscreen sealant              | 1   | \$ 100.00  | 11 40    |
| Rear Bumper reverse sensor          | 1   | \$ 450.00  | Repeal X |
| Sub Total                           |     | \$ 975.00  |          |

| LABOUR CHARGE                                      | QTY | PRICE (\$)  | REMARKS |
|----------------------------------------------------|-----|-------------|---------|
| To check wiring                                    |     | \$ 160.00   | 30      |
| Tuff kote                                          |     | \$ 150.00   | 60      |
| Remove and refix rear exhaust pipe and repair      |     | \$ 160.00   | 11X     |
| Remove and refix rear windscreen                   |     | \$ 180.00   | 120     |
| Remove and replace reverse sensor                  |     | \$ 150.00   | 50      |
| Remove and refix upholstery                        |     | \$ 250.00   | 80      |
| Remove and refix rear boot mechanism               |     | \$ 200.00   | 60      |
| To remove and replace spare part and penal beating |     | \$ 1,800.00 | 800     |
| To spray painting and etc                          |     | \$ 1,600.00 | 1000    |
| Sub Total                                          |     | \$ 4,650.00 |         |

Grand Total \$ 24,543.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

2-6980.61  
252  
5235.45  
90  
2200  
7525.45  
203  
60203