

Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	LH front fender Customized			\$0.00	\$537.00	-10 %	1	\$483.30
02	LH front side mirror assy Customized			\$0.00	\$550.00	-10 %	1	\$495.00
03	LH front door side mirror cover Customized			\$0.00	\$128.00	-10 %	1	\$115.20
04	LH front door Customized			\$0.00	\$881.00	-10 %	1	\$792.90
05	LH front door glass Customized			\$0.00	\$353.00	-10 %	1	\$317.70
06	LH front door glass moulding Customized			\$0.00	\$149.00	-10 %	1	\$134.10
07	LH front door sticker (black) Customized			\$0.00	\$41.00	-10 %	1	\$36.90
08	LH front door handle Customized			\$0.00	\$93.00	-10 %	1	\$83.70
09	LH front door seal 1 Customized			\$0.00	\$6.00	-10 %	1	\$5.40
10	LH front door seal 2 Customized			\$0.00	\$6.00	-10 %	1	\$5.40

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
11	LH front door outer moulding Customized			\$0.00	\$130.00	-10 %	1	\$117.00
12	LH rear door Customized			\$0.00	\$851.00	-10 %	1	\$765.90
13	LH rear door sticker 1 (black) Customized			\$0.00	\$42.00	-10 %	1	\$37.80
14	LH rear door sticker 2 (black) Customized			\$0.00	\$72.00	-10 %	1	\$64.80
15	LH rear door weatherstrip Customized			\$0.00	\$161.00	-10 %	1	\$144.90
16	LH rear door handle Customized			\$0.00	\$93.00	-10 %	1	\$83.70
17	LH rear door handle seal 1 Customized			\$0.00	\$6.00	-10 %	1	\$5.40
18	LH rear door handle seal 2 Customized			\$0.00	\$6.00	-10 %	1	\$5.40
19	LH rear door hinge top Customized			\$0.00	\$42.00	-10 %	1	\$37.80
20	LH rear fender Customized			\$0.00	\$1298.00	-10 %	1	\$1168.20
21	Rear door handle cover Customized			\$0.00	\$45.00	-10 %	1	\$40.50
22	LH rear door handle base Customized			\$0.00	\$50.00	-10 %	1	\$45.00
23	Front door handle cover			\$0.00	\$45.00	-10 %	1	\$40.50

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
	Customized							
24	LH front door handle base Customized			\$0.00	\$50.00	-10 %	1	\$45.00
25	LH front fender arch garnish Customized			\$0.00	\$179.00	-10 %	1	\$161.10
26	LH front door lower garnish Customized			\$0.00	\$171.00	-10 %	1	\$153.90
27	LH rear fender arch garnish Customized			\$0.00	\$148.00	-10 %	1	\$133.20
28	LH rear door lower garnish Customized			\$0.00	\$158.00	-10 %	1	\$142.20
29	LH front door handle switch Customized			\$0.00	\$263.25	-10 %	1	\$236.93
30	LH front door lock Customized			\$0.00	\$322.00	-10 %	1	\$289.80
31	LH rear quarter glass Customized			\$0.00	\$713.00	-10 %	1	\$641.70
Total :\$6830.33								

Materials

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	LH front fender inner shield clips Customized			\$0.00	\$30.00	0 %	1.0	\$30.00
02	LH rear fender inner shield clips			\$0.00	\$30.00	0 %	1.0	\$30.00

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
	Customized							
03	OD/TP CASE (INSURER) Customized			\$0.00	\$11.00	0 %	1.0	\$11.00
								Total :\$71.00

Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	Panel beating Customized		RnR	0.00	\$1200.00	0 %	\$1200.00
02	To check wiring Customized		RnR	0.00	\$30.00	0 %	\$30.00
03	To remove and refit LH front door trim, glass, window regulator, lock to assist workload. Customized		RnR	0.00	\$80.00	0 %	\$80.00
04	To remove and refit LH rear door trim, glass, window regulator, lock to assist workload. Customized		RnR	0.00	\$80.00	0 %	\$80.00
05	To remove and refit LH rear quarter glass Customized		RnR	0.00	\$60.00	0 %	\$60.00
06	To remove and refit inner seat & upholstery to assist work		RnR	0.00	\$100.00	0 %	\$100.00

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
	k load Customized						
07	To remove and refit petrol tank to assist work load Customized		RnR	0.00	\$80.00	0 %	\$80.00
Total :\$1630.00							

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	Spray painting Customized		Full spray	0.00	\$1000.00	0 %	\$1000.00
Total :\$1000.00							

Remarks 2 remarks

2023-04-17 11:47 Assessor Supervisor-Insurlogic 5 45248664708
FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$9,531.33 WITH 9 WORKING DAYS

2022-08-12 11:36 Assessor Supervisor-Insurlogic 1 6584981566
Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic
Amount : \$7590.50
Check: \$1526.62
Repair Duration: 9 days