

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 418854
 TEL: 6746 0674 FAX: 6841 7639

Vehicle No : SLH 3311 J

Make: Toyota Harrier

Date: 26/7/2022

Accident Date: 15/02/2022

Spare parts

QTY	List Price	Price	(S\$)
1	REAR BUMPER	de ✓	1220.866
1	REAR BUMPER LOWER	SLH ✓ 1187	321 ✓
1	RH SIDE RETAINER	X n 256	55 X
1	RH REAR BUMPER REFLECTOR	X n 890.25	65 X
1	REAR BOOT COVER	repair	1680 XR

Spare Parts Subtotal

3341

Special Nett Items Qty

1	Rear bumper clip	n ✓	58.30
1	Rear bumper sensor	X n ✓ 230	360.200
1	Carplate Set	X n	50

460

Labour charges S/N

S/N	Description	(S\$)
1	To tuff coat affected areas	120 X n
2	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	800 600
3	To provide labour charges, workmanship to realign body structure and damaged consistent to the accident	800 300
4	To remove, refit, replace damaged sensor and check up electrical wiring	120 60
5	Labor to remove and refit windscreen	120 X n

Labour charges: Subtotal

960

1960

ESTIMATES PARTS AND LABOR GRAND TOTAL:

5761.00

890.25

230.00

960.00

2080.25

20%

1664.20

4/5 - \$1,650

Resue
Hp 90010068
4 days
13/06/22
@ 1355
LJ
Repair after repair