

(08/11/03) wef

ASS. REC. BY: Rgme

REF:

CC4/LPL22007538/Rp43

B
547K**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMM 6036Kat Workshop m/s My Car Consultantof 60, JLV Lam Hing #05-21

Insured:

LPC

Policy No.:

Claims No.:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

81K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 48K

Veh No:

SMM 6036K

Yr Regn:

2019 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA AXELA 1.5X0 MMU c.c 1498

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

208546

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

BMLFP101418Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

03/08/22

D.O.I.

16/08/22

Survey held at

MY CAR CONSULTANT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S & REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:



: Site Insp (\$

) S + RS SI



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

)

TOTAL

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT CARROS CENTRE
#05-68 (S737869)

TO : NTUC INCOME DATE : 10-Aug-22
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM

VEHICLE DETAILS

: VEHICLE NO : SMM6036K

: MODEL : MAZDA AZELA

THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>de ✓</i>	1	\$ 1,264.40	\$ 1,264.40
2	FRONT BUMPER TOWING COVER <i>cut ✓</i>	1	\$ 45.60	\$ 45.60
3	FRONT BUMPER LOWER GRILLE <i>X</i>	1	\$ 308.50	\$ 308.50
4	FRONT BUMPER REINFORCEMENT <i>?</i>	1	\$ 750.10	\$ 750.10
5	FRONT BUMPER REINFORCEMENT SPONGE <i>?</i>	1	\$ 285.60	\$ 285.60
6	FRONT BUMPER SIDE RETAINER <i>2 X</i>	2	\$ 86.50	\$ 173.00
7	FRONT BUMPER LOWER COVER <i>X</i>	1	\$ 189.20	\$ 189.20
8	FRONT FOG LAMP <i>X</i>	2	\$ 321.00	\$ 642.00
9	FRONT FOG LAMP GARNISH <i>X</i>	2	\$ 277.80	\$ 555.60
10	FRONT GRILLE <i>cut ✓</i>	1	\$ 970.10	\$ 970.10
11	FRONT GRILLE CHROME MOULDING <i>cut ✓</i>	1	\$ 352.20	\$ 352.20
12	FRONT GRILLE EMBLEM <i>new ✓</i>	1	\$ 104.90	\$ 104.90
13	FRONT GRILLE TOP GARNISH <i>?</i>	1	\$ 320.50	\$ 320.50
14	FRONT GRILLE SUPPORT BRACKET <i>?</i>	2	\$ 89.00	\$ 178.00
15	BONNET LOCK <i>X</i>	1	\$ 298.20	\$ 298.20
16	HEADLAMP <i>2H-? / LH-X</i>	<i>12</i>	\$ 1,623.30	\$ 3,246.60
17	FRONT SUPPORT PANEL <i>X</i>	1	\$ 886.90	\$ 886.90
18	FRONT SUPPORT PANEL TIE BAR <i>X</i>	1	\$ 287.60	\$ 287.60
19	RADIATOR AIR GUIDE <i>X</i>	1	\$ 135.30	\$ 135.30
20	FRONT SUPPORT PANEL UPPER GARNISH <i>X</i>	1	\$ 68.00	\$ 68.00
21	FRONT SUPPORT PANEL LOWER GARNISH <i>X</i>	2	\$ 51.10	\$ 102.20
22	A/C CONDENSER <i>X</i>	1	\$ 976.30	\$ 976.30
23	AIR INTAKE DUCT ASSY <i>X</i>	1	\$ 188.90	\$ 188.90
24	HORN <i>X</i>	2	\$ 96.30	\$ 192.60
25	WIPER WASHER TANK <i>X</i>	1	\$ 169.30	\$ 169.30

26	RADIATOR <i>X</i>	1	\$ 1,527.50	\$ 1,527.50
27	RADIATOR RESERVE TANK <i>X</i>	1	\$ 92.90	\$ 92.90
28	REVERSE SENSOR <i>?</i>	2	\$ 290.00	\$ 580.00
29	REVERSE SENSOR WIRE HARNESS <i>X</i>	1	\$ 170.60	\$ 170.60
30	REAR BUMPER <i>de</i>	1	\$ 1,023.90	\$ 1,023.90
31	REAR BUMPER REFLECTOR <i>X</i>	2	\$ 154.30	\$ 308.60
32	REAR BUMPER TOWING COVER <i>mis</i>	2	\$ 58.30	\$ 116.60
33	REAR BUMPER RETAINER <i>?</i>	2	\$ 79.80	\$ 159.60
34	REAR BUMPER CENTER BRACKET <i>?</i>	1	\$ 19.80	\$ 19.80
35	REAR BUMPER REINFORCEMENT <i>?</i>	1	\$ 796.70	\$ 796.70
36	REAR BUMPER SIDE COVER <i>X</i>	2	\$ 72.30	\$ 144.60
37	BOOT LID <i>bt</i>	1	\$ 1,499.40	\$ 1,499.40
38	BOOT LID LAMP <i>LH-? / RH-Cm</i>	2	\$ 565.40	\$ 1,130.80
39	BOOT LID HINGE <i>X</i>	2	\$ 120.80	\$ 241.60
40	BOOT LID LOCK ASSY <i>X</i>	1	\$ 280.40	\$ 280.40
41	BOOT LID STRIKER <i>X</i>	1	\$ 56.20	\$ 56.20
42	BOOT LID STOPPER <i>de</i>	2	\$ 18.10	\$ 36.20
43	BOOT LID EMBLEM <i>m</i>	1	\$ 108.90	\$ 108.90
44	BOOT LID EMBLEM "AXELA" <i>m</i>	1	\$ 94.70	\$ 94.70
45	BOOT LID EMBLEM "SKYACTIVE" <i>m</i>	1	\$ 87.50	\$ 87.50
46	BOOT LID WEATHER STRIP <i>m</i>	1	\$ 172.80	\$ 172.80
47	BOOT LID INNER TRIM <i>X</i>	1	\$ 398.70	\$ 398.70
48	BOOT LID DETECTOR <i>X</i>	1	\$ 314.00	\$ 314.00
49	BOOT LID DETECTOR INNER <i>X</i>	1	\$ 311.00	\$ 311.00
50	TAILLAMP <i>?</i>	2	\$ 1,040.40	\$ 2,080.80
51	TAILLAMP PANEL <i>X</i>	2	\$ 398.00	\$ 796.00
52	REAR END PANEL <i>bt / photo</i>	1	\$ 676.30	\$ 676.30
53	REAR END PANEL TOP GARNISH <i>?</i>	1	\$ 180.10	\$ 180.10
54	REAR FLOOR PANEL <i>X</i>	1	\$ 1,086.90	\$ 1,086.90
55	REAR FENDER <i>repair</i>	2	\$ 1,159.00	\$ 2,318.00
56	REAR FENDER SIDE INNER TRIM <i>X</i>	2	\$ 644.00	\$ 1,288.00
57	REAR FENDER INNER COWLING <i>X</i>	2	\$ 159.00	\$ 318.00
58	REAR FLOOR PANEL MAT <i>X</i>	1	\$ 294.20	\$ 294.20
59	REAR FLOOR PANEL TOP SPONGE <i>X</i>	1	\$ 389.00	\$ 389.00
60	REAR FLOOR PANEL TOP BOARD <i>X</i>	1	\$ 245.70	\$ 245.70
61	REAR EXHAUST PIPE <i>X</i>	1	\$ 985.20	\$ 985.20
62	REAR EXHAUST MOUNTING <i>X</i>	2	\$ 19.20	\$ 38.40

TOTAL PRICE	\$ 33,061.20
LESS 20%	\$ 6,612.24
SUB TOTAL PRICE	\$ 26,448.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	NUMBER PLATE <i>ms / front</i>	<i>12</i>	\$ 50.00	\$ 100.00	<i>35</i>
2	FRONT BUMPER CLIP SET <i>ms /</i>	1	\$ 65.00	\$ 65.00	<i>30</i>
3	FRONT BUMPER LOWER GRILLE CLIP SET <i>ms /</i>	1	\$ 38.00	\$ 38.00	<i>20</i>
4	BONNET INSULATOR CLIP SET <i>x</i>	1	\$ 65.00	\$ 65.00	<i>x</i>
5	FRONT GRILLE CLIP SET <i>ms /</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
6	FRONT SUPPORT PANEL SEALANT <i>x</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
7	RADIATOR COOLANT <i>x</i>	3	\$ 45.00	\$ 135.00	<i>x</i>
8	REAR NUMBER PLATE <i>x</i>	1	\$ 50.00	\$ 50.00	<i>x</i>
9	REAR BUMPER CLIP SET <i>ms /</i>	1	\$ 65.00	\$ 65.00	<i>30</i>
10	TAIL LAMP CLIP SET <i>x</i>	1	\$ 35.00	\$ 35.00	<i>10 x</i>
11	TAIL LAMP PANEL SEALANT <i>x</i>	2	\$ 80.00	\$ 160.00	<i>x</i>
12	REAR FENDER SIDE INNER TRIM RH CLIP SET <i>ms /</i>	1	\$ 65.00	\$ 65.00	<i>30</i>
13	REAR END PANEL SEALANT <i>ms /</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
14	REAR FLOOR PANEL SEALANT <i>x</i>	2	\$ 80.00	\$ 160.00	<i>x</i>
15	REAR FLOOR PANEL INSULATOR <i>x</i>	1	\$ 250.00	\$ 250.00	<i>x</i>

TOTAL \$ 1,378.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$ 1,000.00	<i>300</i>	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 800.00	<i>200</i>	
3	DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.	\$ 180.00	<i>x</i>	
4	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	\$ 150.00	<i>x</i>	
5	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 80.00	<i>30?</i>	
6	REMOVE AND INSTALL ENGINE WIRE HARNESS. RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER.	\$ 150.00	<i>x</i>	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,800.00	<i>1000</i>	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,400.00	<i>1000</i>	

3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 120.00	X	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 150.00	40	
5	RENEW REAR FLOOR INSULATOR.	\$ 100.00	X	
6	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	\$ 150.00	X	
7	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 80.00	30	
8	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSITION.	\$ 200.00	X	
9	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	30	
10	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY. RE-ALIGN TO POSITION.	\$ 200.00	60	
11	APPLY TUFF COATING TREATMENT.	\$ 200.00	80	

TOTAL

\$ 6,860.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 27,826.96
TOTAL LABOUR COST : \$ 6,860.00
TOTAL REPAIR COST : \$ 34,686.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Done
Hp 90010068
8 days
4/1
10/08/22 @ 1710
Res after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/08/2022 00:17 (SGT)
Reported by	Driver
Date of Accident	03/08/2022 12:15 (SGT)
Exact Location of Accident	Alexandra Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM6036K
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Orange Express
Company Reg No	5XXXX547K
Email Address	kim@freshcars.sg
Mobile Phone No	(Phone) +65-88156670
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	Axela
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	0

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D22MFL0004228

DRIVER

Name of Driver	Mohamed Azahar Bin Abd Rahman
NRIC No	SXXXX020F
Date Of Birth	02/07/1969
Occupation	Outdoor

State Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

01/11/1996
25 YEARS AND 9 MONTHS
Male
(Phone) +65-88156670
-
kim@freshcars.sg
Blk 204 Marsiling Drive
#05-208
730204
No
Hirer
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface
Chain Collision
Drizzling
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 3
Was anybody injured in the Accident? Yes
Was any injured conveyed to hospital by ambulance? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

PASSENGER 1

Name -
Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
Police Station Name Bukit Panjang North Neighbourhood Police Post
Police Station Address Blk 27 Marsiling Drive Singapore 730027
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

Refer to police report - T/20220805/2067

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA5784J
Vehicle Manufacturer -

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	Wang Mingzhou
Work Permit No	0XXXX2744
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLV255Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Rene Wu Cairu
NRIC No	SXXXX547H
Contact Number	(Phone) +65-90723243
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Mohamed Azahar Bin Abd Rahman
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	Body
Injured person in which vehicle?	SMM6036K
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstances of the Accident

Refer police file

Declaration

I/We declare the foregoing particulars are true in every respect.

ORANGE EXPRESS
UEN: 53388547K

Policyholder's Signature / Date &
Time

Ad

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

ORANGE EXPRESS
UEN: 53388547K

Policyholder's Signature / Date &
Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



A : SMN 6036K

B : GEA 5784J

C : SLV 2552

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	547K
Vehicle No:	SMM6036K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Aug 2022
Vehicle Make:	MAZDA
Vehicle Model:	AXELA 1.5XD AUTO
Primary Colour:	Black
Manufacturing Year:	2019
Engine No:	5530435841
Chassis No:	8MLFP101418
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$25,066.00
Original Registration Date:	05 Jul 2019
First Registration Date:	05 Jul 2019
Transfer Count:	1
Actual ARF Paid:	\$17,093.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jul 2029
PARF Rebate Amount:	\$12,819.00
COE Expiry Date:	04 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,589.00
COE Rebate Amount:	\$19,717.00
Total Rebate Amount:	\$32,536.00

The information contained herein is correct as at 11 Aug 2022

OK

Mazda Axela Diesel 1.5A

Overview

Financial

Accessories

Similar

Research

Photos

Map



Member of:



AUTOMOBILE IMPORTERS
& EXPORTERS ASSOCIATION (SINGAPORE)
新加坡汽車進出口商協會



Price	\$81,800		
Depreciation ⓘ	\$10,630 /yr View models with similar depre	Reg Date	01-Jul-2019 (6yrs 10mths 19days COE left)
Mileage	33,000 km (10.6k /yr)	Manufactured ⓘ	2019
Road Tax ⓘ	\$1,084 /yr	Transmission	Auto
Dereg Value	\$31,424 as of today (change)	Fuel Type	Diesel (Euro 5 Engine and Above)
COE ⓘ	\$27,000	OMV ⓘ	\$25,066
Engine Cap	1,498 cc	ARF ⓘ	\$17,093
Curb Weight ⓘ	1,360 kg	Power	77.0 kW (103 bhp)