



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S CHINA TAIPING INSURANCE
(SINGAPORE) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Insured 3S TRANSPORT PTE LTD

Policy VFX/P2260261/0042

ESTIMATE BILL

GST Reg. No: 199800107D

Date: 6/8/2022

Our Case Ref. SC22/08/103/43T-TP

Accident Date 3/8/2022

Damaged Vehicle No: PC7669U

S/no	Description	QTY	Price	Amount	Remark
Replaced Parts					
1	REAR BUMPER <i>4/</i>	1 PC	\$ 1,850.00	\$ 1,850.00	537 40 XR 15 320 X 50
2	REAR REVERSE SENSOR <i>nm / 2pc</i>	2 PC	\$ 268.50	\$ 268.50	
3	REAR NUMBER PLATE WITH HOLDER <i>cm / 1</i>	1 PC	\$ 80.00	\$ 80.00	
4	REAR PANEL INNER <i>repair</i>	1 PC	\$ 1,980.00	\$ 1,980.00	
5	INFORMATION STICKER <i>nm</i>	1 PC	\$ 80.00	\$ 80.00	
6	REAR NUMBER PLATE LIGHT <i>cm</i>	1 PC	\$ 385.60	\$ 385.60	
7	REAR EMBLEM <i>nm</i>	1 PC	\$ 186.50	\$ 186.50	
8	ARTWORK <i>X nm</i>	1 PC	\$ 450.00	\$ 450.00	
9	SUNDRIES <i>/ nec</i>		\$ 200.00	\$ 200.00	
Labour Charges					
1	LABOUR TO REMOVE, REINSTALL AND CHECK <i>(curv)</i>			\$ 800.00	100
2	LABOUR TO REMOVE, REPAIR AND REINSTALL REAR BUMPER, REAR PANEL, TAILGATE <i>@ 640 X 2.5</i>			\$ 4,000.00	1600
3	LABOUR TO RESPRAY REAR BUMPER, REAR PANEL, TAILGATE. <i>@ 640 X 2</i>			\$ 2,800.00	1280
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK			\$ 350.00	80

TOTAL \$13,430.60 13,699.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2730.00

3060.00

5790.00

208

4632

45-84,600

Panel

Hp 90010068

4 days

4/5

11/10/22 @ 1350

Res after repair