

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0669/2022/EQ
DATE : 8-Aug-22
WIP : 36485

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/8/2022

YOUR INSURED VEH NO : SMR 9187 L

SPF ACCIDENT CLAIM SECTION

LOGISTICS SUPPORT & SERVICES DIVISION

POLICE LOGISTICS DEPARTMENT

POLICE LOGISTICS BASE

1 HEMMANT ROAD

SINGAPORE 438675

Attn: Motor Claims Dept

OWNER'S NAME : MR. LAWRENCE WONG SHYUN TSAI
ADDRESS : 8 NASSIM HILL
#05-06
SINGAPORE 258484
TELEPHONE : HP +65 92965470
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100435261-02
VEHICLE NO : SFD 992 U
MODEL CODE : AUDI Q3 2.0 TFSI QU
MODEL YEAR : 27/10/2015
ENGINE NO : CUL 016176
CHASSIS NO : WAUZZZ8U4GR032932
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Aug-22
PLACE OF ACCIDENT : TRAFFIC LIGHT JUNCTION OF ORCHARD BOULEVARD AND
GRANGE ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFD 992 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00 /	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00 /	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00 X	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	✓
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,600.00 /	(p/h) ✓
SUB-TOTAL LABOUR CHARGES		: \$ 3,440.00	

3,440

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFD 992 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD EAR END PANELLING. TO REPAIR		
7	SPARE WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 5,000.00 S 2800 800	2500 4000
8	TO RESPRAY REAR BUMPER, REAR LOWER SPOILER, REAR LID, HINGES, BOTH REAR WHEEL ARCH TRIMS, 400 SPARE WHEEL HOUSING AND REAR END PANELLING.	S 5,500.00 4.5 x 800 + 400	2875 4000
9	TO RENEW LHS REAR AND CENTER EXHAUST SILENCER AND ALIGN TO POSITION.	S/N S 480.00	/
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S 192.00	/
TOTAL LABOUR CHARGES		: \$ 14,612.00	

8672


Car in

11/8/22

wip: 36485

PREMIUM AUTOMOBILES

Bena



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 992 U

SPF - ?

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1 S	1,682.00	
2	REAR BUMPER FIXING PARTS	1 S	129.00	
3	REAR BUMPER SPOILER	1 S	979.00	
4	REAR DIFFUSER	1 S	786.00	
5	REAR BUMPER TOW EYE COVER - LH / RH	2 S	77.00	
6	REAR BUMPER TAIL LIGHT - LH / RH	1 S	1,026.00	513
7	REAR BUMPER TAIL LIGHT - LH / RH	1 S	TBC	?
8	REAR LICENCE PLATE LIGHT	2 S	128.00	
9	REAR BUMPER CARRIER	1 S	693.00	
10	REAR BUMPER GUIDE SECTION - LH / RH	2 S	224.00	
11	REAR FOAM FILLER PIECE - LH	1 S	96.00	
12	REAR PARKING AID SENSOR	2 S	531.00	
13	REAR PARKING AID SEAL RING	4 S	6.00	
14	REAR BUMPER WIRING SET	1 S	572.00	
15	REAR LID	1 S	4,142.00	
16	REAR LID ATTACHMENT PARTS	1 S	201.00	
17	REAR LID HINGE	2 S	510.00	
18	CHAFE GUARD	2 S	6.00	
19	BUNGS	4 S	14.00	
20	REAR LID LOCK	1 S	190.00	
SUB TOTAL SPARE PARTS			\$ 11,992.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

8301

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 992 U


			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET LOCK COVER X NN	1	\$ 8.00	
22	BONNET LOCK ACTUATOR PUSH BUTTON / CR	1	\$ 200.00	
23	BONNET LOCK ACTUATOR PUSH BUTTON COVER / MC	1	\$ 18.00	
24	REAR FLAP GASKET (Rubber Tally) / CR	1	\$ 229.00	
25	REAR STRIKER PLATE ? X NN	1	\$ 888.00	
26	REAR SPOILER FIXING PARTS / MC	1	\$ 91.00	
27	ADHESIVE TAPE / LC	1	\$ 10.00	
28	PACKING, ADHESIVE / LC	1	\$ 21.00	
29	AUDI EMBLEM CHROME / MC	1	\$ 144.00	
30	"Q3" INSCRIPTION CHROME / MC	1	\$ 104.00	
31	"TFSI" INSCRIPTION CHROME / MC	1	\$ 104.00	
32	"QUATTRO" INSCRIPTION CHROME / MC	1	\$ 104.00	
33	REAR WINDOW / MC	1	\$ 1,064.00	
34	WINDOW PRIMER / MC	1	\$ 22.00	
35	REAR LID SPOILER - LH / RH / MC	2	\$ 270.00	
36	WIPER MOTOR X NN	1	\$ 498.00	
37	ELBOW FITTING X NN	2	\$ 30.00	
38	REAR CORRUGATED PIPE X NN	1	\$ 93.00	
39	REAR CROSS PANEL / OP	1	\$ 329.00	
40	REAR REINFORCEMENT CROSS PANEL / NN	1	\$ 971.00	
SUB TOTAL SPARE PARTS			: \$ 5,198.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

3681

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 992 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/N	NETT	
41	REAR CROSS PANEL TRIM ? CR4	1	S	806.00	
42	REAR LID TRIM PANEL X nn	1	S	533.00	
43	REAR SILENCER / B1 (P4)	1	S	1,562.00	
44	DUAL CLIP - n	2	S	135.00	
45	FRONT RETAINING RING - n	1	S	20.00	
46	REAR RETAINING RING - n	2	S	40.00	
47	EXHAUST RETAINER - n	2	S	99.00	
48	EXHAUST CENTRE SILENCER ? X nn	1	S	1,042.00	
49	DUAL CLIP ? X nn	1	S	68.00	
50	DUAL CLIP ? X nn	2	S	135.00	
51	EXHAUST TAILPIPE CHROME TRIM SET / n	1		TBC ?	
52	REAR SILENCER HEAT SHIELD ? X nn	1	S	257.00	
53	REAR OUTER WHEEL SPOILER UNDERBODY TRIM - LH ?	1	S X nn	138.00	
54	REAR WHEEL HOUSING LINER - LH X nn	1	S	260.00	
55	REAR WHEEL COVER - LH / RH - n	(2)	S	1,114.00	
56	REAR BUMPER AERIAL ACCESS ? X nn	1	S	79.00	
57	REAR WINDSCREEN SEALANT / n	S/N	S	200.00	
58	ACRYLIC SEALANT - n	S/N	S	180.00	
59	CAVITY WAX / n	S/N	S	140.00	
60	STONE CHIP / n	S/N	S	180.00	
SUB TOTAL SPARE PARTS		:	\$	6,988.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

4476

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 992 U


S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	METAL FILLER POWDER <i>✓</i>	S/N	\$	280.00	
62	REAR NO PLATE <i>37</i>	S/N	\$	60.00	
63	SUNDRIES <i>* NN-</i>		\$	? 400.00	
TOTAL SPARE PARTS		:	\$	24,918.00	
TOTAL LABOUR CHARGES		:	\$	14,612.00	
GRAND TOTAL		:	\$	39,530.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

340

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
10/8/22, 3:30p

W R
P/P
By
10 days
add 1 day
= 11 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER


ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W


SPF ACCIDENT CLAIM SECTION
LOGISTICS SUPPORT & SERVICES DIVISION
POLICE LOGISTICS DEPARTMENT
POLICE LOGISTICS BASE
1 HEMMANT ROAD
SINGAPORE 438675
Attn: Motor Claims Dept

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0669/2022/EQ
15-Aug-22
CHANG
1 of 1
SFD 992 U
AUDI Q3 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR LHS REAR FENDER.	\$ 800.00	400
2	TO RESPRAY LHS REAR FENDER.	\$ 1,600.00	800
GRAND TOTAL		\$ 2,400.00	1200

For Premium Automobiles Pte Ltd



Authorised Signature

Steve (LKK)

15/8/22

Total = 29,710

Add 1 Lys