

Not Authorized
 Repair by paint
 81562.85

AAD2208-

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHC5509G

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

10 AUG 2022

SHC5509G
 JTKB3FU203092595
 TOYOTA
 PRIUS GEN 4
 03/08/2022
GBE2438H/GREAT AMERICAN
 06/11/2020

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ 1,300.70 ✓
1 LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$ 603.20 X
1 MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$ 38.60 X
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ 193.50 X
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ 390.60 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$ 926.00 X
1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$ 321.10 X
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ 97.50 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ 238.30 X
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ 43.50 ✓
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ 13.30 ✓
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ 26.30 ✓
TOTAL	\$ 4,303.20
25%	\$ 1,075.80
	\$ 3,227.40

Special Nett	
1 DOOR STICKER TRANSCAB	\$ 100.00 60sn
2 DOOR TRIM CLIP	\$ 150.00 X
2 DOOR WEATHERSTRIP CLIP	\$ 160.00 X
TOTAL	\$ 410.00
TOTAL PARTS	\$ 3,637.40

LABOUR	
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$ 240.00 30l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ 380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$ 1,600.00 200l
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$ 380.00 X
Putty And Spray Painting Of The Affected Portion.	\$ 1,600.00 220l
To transfer of tire, rim and on wheel balancing.	\$ 170.00 X
To Check Electrical Lighting Concerned.	\$ 170.00 15l

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHC5509G

AAD2208-

STATEMENT

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To remove and refit of fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
TOTAL	\$	4,930.00
Over All Total	\$	8,567.40

(PART-BY-PART) Repair Days

20 Days

2 days

03/03/2022 18:39 (SGT)
 02/03/2022 10:30 (SGT)
 BLK 04 REDHILL LANE OPEN SPACE CARPARK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Toyota
 Prius
 SDR HATCHBACK (AUTO)

Private hire
 No - Claiming third party
 Taxi
 Auto
 T-67

AAA Insurance Pte Ltd
 VFX42417807

TAY MENA FOON
 84000360
 2810 1566
 Customer