

Not Authored
Resurvey B4 paint

AAD2208-

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHC5509G

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

1 0 AUG 2022

SHC5509G
JTDKB3FU203092595
TOYOTA
PRIUS GEN 4
03/08/2022
GBE2438H/GREAT AMERICAN
06/11/2020

PART

LIST

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 LOCK ASSY, FRONT DOOR W/MOTOR, RH
- 1 MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH
- 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH
- 1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, RH
- 1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH

\$	<i>Rs</i>	1,300.70	✓
\$	<i>R</i>	603.20	X
\$	<i>Sm</i>	38.60	X
\$	<i>Sm</i>	193.50	X
\$	<i>Sm</i>	390.60	X
\$	<i>Sm</i>	926.00	X
\$	<i>Sm</i>	321.10	X
\$	<i>R</i>	110.60	X
\$	<i>R</i>	97.50	X
\$	<i>R</i>	238.30	X
\$	<i>Rs</i>	43.50	—
\$	<i>Rs</i>	13.30	—
\$	<i>Rs</i>	26.30	✓
TOTAL \$		4,303.20	
25% \$		1,075.80	
\$		3,227.40	

Special Nett

- 1 DOOR STICKER TRANSCAB
- 2 DOOR TRIM CLIP
- 2 DOOR WEATHERSTRIP CLIP

\$	<i>Rs</i>	100.00	<i>60sm</i>
\$	<i>Rs</i>	150.00	X
\$	<i>Rs</i>	160.00	X
TOTAL \$		410.00	

TOTAL PARTS \$ 3,637.40

LABOUR

- To Rust-Proofing and apply undercoat Of The Affected Areas.
- To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.
- Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same
- To transfer of rear end panel fittings, attachment to facilitate bodywork repair.
- Putty And Spray Painting Of The Affected Portion.
- To transfer of tire, rim and on wheel balancing.
- To Check Electrical Lighting Concerned.

\$		240.00	<i>30l</i>
\$	<i>Rs</i>	380.00	X
\$		1,600.00	<i>200l</i>
\$	<i>Rs</i>	380.00	X
\$		1,600.00	<i>220l</i>
\$	<i>Rs</i>	170.00	X
\$		170.00	<i>15l</i>

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHC5509G

AAD2208-

To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00 <i>X</i>
To remove and refit of fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00 <i>X</i>
TOTAL	\$		4,930.00
Over All Total	\$		8,567.40

(PART-BY-PART) Repair Days

20 Days
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/08/2022 18:09 (SGT)
Reported by Driver
Date of Accident 03/08/2022 10:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information BLK 84 REDHILL LANE OPEN SPACE CARPARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC5509G
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address Claims@transcab.com.sg
Mobile Phone No (Phone) +65-62876666
Alternative Phone No -


VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant 5DR HATCHBACK (AUTO)
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1767

INSURANCE COMPANY


Name of Insurance Company AXA Insurance Pte Ltd
Policy Number / Cover Note Number VFX/P2413997

DRIVER
Name of Driver TAY MENG SOON
NRIC No SXXXX936J
Date Of Birth 26/10/1960
Occupation Outdoor



VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
ANG QI HAO. VICTOR

Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: