

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22007549/KCM4**Date:** 26/09/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP306175
Claimant Vehicle No :	SKJ6013R	Insured Vehicle No :	SKW3185D
Date of Loss:	05/08/2022	Nature of Claim:	TP
		Claim No:	MPC03582/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ6013R		
Make & Model:	JAGUAR XF, 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC (A)	Engine No:	4025120224DT
Reg. Date:	22/04/2013 (Man. Year: 2013)	Chassis No:	SAJAC0566DDS83982
Colour:	Metallic Beige	Odometer:	221863 km
Engine Capacity:	2179 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 ZR18	Rear Tyre Size:	245/45 ZR18
Front Left Side:	Accelera 7 mm	Rear Left Side:	Acceieta 7 mm
Front Right Side:	Accelera 7 mm	Rear Right Side:	Acceieta 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,144.51	5,530.06	614.45	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,930.00	390.00	16.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,464.51	7,460.06	1,004.45	11.87
Approved Total (Overridden) (S\$)		5,950.00		
(S\$)	8,464.51	5,950.00	2,514.51	29.71
+ GST 7.00/7.00% (S\$)	592.52	416.50	176.02	29.71
Nett Amount (S\$)	9,057.03	6,366.50	2,690.53	29.71

INSPECTION

Date of Assignment:	08/08/2022	
Date Inspected:	25/08/2022	Inspected At: LAI HUAT (MENG KEE) MOTOR PTE LTD (HQ) 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Sep 2022)

Parts: 143 JAGUAR XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKJ6013R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	2,400.00 F	*2,400.00 FN
2	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	155.00 F	*155.00 FN
3	1		*REAR DOOR LH	Bent	2,380.00 F	*2,380.00 FN
4	1		*REAR DOOR WEATHERSTRIP LH	Necessary	140.00 F	*140.00 FN
5	1		*FRONT DOOR LOCK MECHANISM LH (FAULTY)	Dented	558.99 F	*558.99 FN
6	1		*FRONT DOOR FRAME TRIM LH (UPON REMOVAL, IT CRACKED)	Cracked	510.52 F	*510.52 FN

F=Franchise part. N=NetItemDisc.

Sub Total (\$)	6,144.51	6,144.51
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	614.45
Total Parts (\$)	6,144.51	5,530.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK/ERASE FAULT CODES AFTER REPAIR	New	120.00	80.00
2	TO KNOCK DENTS ON REAR FENDER LH AND RENEW OF PARTS	New	700.00	600.00
3	TO SPRAY PAINT (INCLUDING REAR SPORT RIM LH, SIDE SKIRT LH + BLEND ROOF PANEL LH)	New	1,500.00	1,250.00
Gross Labour Cost (\$)			2,320.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >