

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

NS/INC22025521UC

**ASSIGNMENT**

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

27/11/17690

Veh No:

SH7333B

Yr Regn:

25/05/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A /

Make:

Toyota prius Hybrid c.c

1798

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

621473

T/Radio: Insured / Std / NI / NA

Eng/No:

JTDKB3FU103556816

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/08/22

D.O.I.

8/8/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/8/22 informed Juman: 1/5 & 2600 @ 11.25am. not agree; 3 days  
(Red \$1,826.82/41%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

## REPAIR ESTIMATE\*

**DOA: 08.08.22**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY		20/02	\$503.04
1	REAR BUMPER CENTRE MLDG		Dis	\$654.96
1	REAR BUMPER BEAM		100	\$318.80
1	REAR FLOOR UNDER COVER		17	\$220.50
10	REAR BUMPER CLIPS		her	\$22.00
1	BOOTLID OUTER COVER		negot	\$1,054.71
1	BOOTLID EMBLEM - PRIUS		her	\$62.14
1	BOOTLID EMBLEM - HYBRID		her	\$62.14
1	BOOTLID EMBLEM - STAR		17	\$81.43
1	REAR BUMPER TOW COVER		can	\$82.70
	<b>SUB TOTAL</b>			<b>\$3,062.42</b>
	<b>LESS 25%</b>			<b>\$76,535.00</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$2,296.82</b>
	BOOTLID COMFORT LOGO 102		her	\$30.00
	BOOTLID COMFORT TEL.NOS LOGO 102		her	\$30.00
	BOOTLID APPS LOGO 102		her	\$40.00
	REVERSE SENSOR 102		SUR	\$180.00
	REAR BUMPER MAT		SN 7011	\$50.00
	ADVERTISEMENT LOGO - BUMPER		SN her	\$50.00
	ADVERTISEMENT LOGO - FENDER		SN her	\$200.00
				<b>\$580.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING -			\$800.00
	SPRAY PAINT			\$600.00
	REMOVE/REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	TUFF KOTE			\$50.00
	<b>TOTAL LABOUR</b>			<b>\$1,550.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,426.82</b>
				<b>\$2760.82</b>
				<b>259</b>
				<b>2070.36</b>

Not Authorized  
Lexus Marcus  
90096604  
marcus@lkkauto.com  
2/c 2600  
3 days.  
Take photo After repair

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To resurvey before/after damaged parts, fitting resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modifications is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305525858

Date 15.08.22

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : Mr MARCUS

Vehicle Reg No. SH 7333B


Date of Accident : 08.08.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SLL9436L
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**

~~\$2150.00~~  
4/5 @ 2600
3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :   
Name : **JUMANI**  
Tel : 62148315  
Fax : 65468156

Signature : \_\_\_\_\_  
Name : **MARCUS**  
Date : \_\_\_\_\_

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: